ļ

ł

HAZARDOUS MATERIAL/WASTE MARC CENTERS

CON	TENTS	PAGE	B. Cold Cathode Tubes -
			Safety Precautions
1.	GENERAL	1	C. Mercury Relays -
2.	INTRODUCTION	2	Clean-Up Procedures
3.	IDENTIFICATION OF HAZARDOUS		D. Mercury Relays -
	MATERIAL/WASTE	4	Safety Precautions
4.	HAZARDOUS MATERIAL/WASTE	4	E. Mercury Vapor Tubes -
	4.01 Cold Cathode Tubes	4	Clean-Up Procedures
	Identification	4	F. Mercury Vapor Tubes -
	Handling	5	Safety Precautions
	Storage/Packaging	5	G. Polychlorinated Biphenyls -
	Shipping	6	Clean-Up Procedures
	4.02 Units Containing Mercury	7	H. Polychlorinated Biphenyls -
	Identification	7	Safety Precautions
	Handling	8	EXHIBITS
	Storage/Packaging	8	1. Southwestern Bell's Responsibilities
	Shipping	8	2. Returned Material Notice
	4.03 Polychlorinated Biphenyls	9	TABLES
	Identification	9	A. Cold Cathode Tubes
	Handling	10	B. Test Sets Containing Mercury
	Storage/Packaging	10	C. Spare Packs Containing Mercury
	Shipping	11	D. Mercury Relays
	4.04 Batteries	11	E. Mercury Switches
	Wet Cells	11	F. Mercury Vapor Tubes
	Other	11	G. PCB Capacitors
	4.05 Beryllium Oxide	11	H. PCB Capacitors Over Three (3) Pounds
	Identification	11	I. PCB General Trade Names
	Handling	11	J. Power Equipment Containing PCB's
	Storage/Packaging	11	FIGURES
	Shipping	12	1. Cold Cathode Tubes
5.	TRAINING	12	2. Mercury Relays
6.	CONTINGENCY PLAN	12	2A.Mercury Vapor Tubes
7.	GLOSSARY	13	3. PCB Capacitors
	7.02 Acronyms	13	
	7.03 Terms	16	1.0 GENERAL
ATT	FACHMENTS		
	A. Cold Cathode Tubes -		1.01 This section provides procedures for
	Clean-Up Procedures		Material Reprocessing and
			Consolidation (MARC) Operations supervisors
			to follow for the control of hazardous waste

SW 745-010-902

and material resident in Telephone Company-owned equipment. All procedures outlined herein should be integrated with the Company policies as established and conveyed through the Disposition Services District of the Procurement-Logistics organization.

1.02 When this practice is reissued, the reason(s) for reissue will be indicated in this paragraph.

2.0 INTRODUCTION

2.01 The Environmental Protection Agency

(EPA) has developed a system for regulating the management of hazardous wastes. In addition, the Department of Transportation (DOT) has rules prescribing certain requirements for packaging, identifying and manifesting hazardous waste and materials being transported. The purpose of DOT regulations is to regulate those items that are determined capable of posing unreasonable risks to health, safety and property during transport. Since much of the scrap received at the MARC Centers may contain hazardous wastes and/or material, these regulations may apply to scrapping procedures related to equipment designated for disposal. It is the MARC Operations supervisor's responsibility for ensuring that all hazardous wastes and/or material are properly removed and disposed of prior to the start of any dismantling, sorting, or upgrading procedures.

- 2.02 Hazardous materials, as defined by the DOT, are classified as:
 - o Explosives
 - o Flammable solids and liquids
 - o Oxidizing material

- o Corrosive material
- o Compressed gases
- o Organic peroxides
- o Poisons, etiological agents and radioactive materials
- o Other regulated materials (ORM)
- 2.03 Hazardous materials known to exist in Telephone Company-owned equipment
- are:
- o Units containing mercury (gas or liquid)
- o Polychlorinated Biphenyls (PCB's)
- o Cold Cathode Tubes containing radioactive material
- o Microwave Equipment containing Beryllium Oxide
- o Wet Cell Batteries containing electrolyte (sulfuric acid)

2.04 Exhibit 1 of this outline is issued by the General Headquarters Environmental group in the Support Services organization and prescribes the overall company responsibilities concerning the federal regulations. It includes a synopsis of the regulations, the types of materials involved and general Company procedures.

2.05 As outlined in Exhibit 1, there are distinct differences between hazardous waste and hazardous materials as they relate to EPA and DOT regulations. These substances will be referred to throughout this section as hazardous material/waste. 2.06 Examples of Telephone Company-owned equipment that could be received at MARC Centers which may contain hazardous material/waste are:

- o Central Office Equipment
- o Private Branch Exchange Systems
 (PBX's)
- o Key Telephone Systems
- o Station Equipment
- o Coin Telephone Sets and Booths
- o Test Sets

NOTE: This is not an all inclusive listing of equipment containing hazardous material/waste. It is merely a sample of equipment known to contain hazardous material/waste.

2.07 All scrap materials received at MARC

Center locations must have the hazardous material/waste identified, removed, staged and shipped in accordance with the regulations prescribed by the government. Equipment received at the MARC Center should have the hazardous material/waste removed by contractors or Telephone Company personnel prior to receipt, it is the ultimate responsibility of the MARC Operations supervisor to ensure that all hazardous material/waste is removed prior to final disposition of the scrap.

 (a) The Returned Material Notice (RMN) FA Form SW-6381, issued by the equipment engineer for processing of scrap should indicate on the RMN that Hazardous Mat'l/Waste has or has not been removed. Exhibit 2 illustrates how to mark the RMN. HAZARDOUS MAT'L/WASTE REMOVED YES__ NO__

(b) Upon receipt of a scrap shipment at the MARC Center, the RMN should
be checked for this entry. When the RMN indicates that hazardous material/waste
has been removed and hazardous
material/waste is found in the
equipment, the SWB employee in charge of the removal should be notified to
resolve these discrepancies.

2.08 It is the responsibility of the MARC Operations supervisor to ensure that all <u>contracted personnel</u> involved in the handling of hazardous material/waste perform these contracted duties in accordance with Southwestern Bell, EPA and DOT regulations.

2.09 Further, the MARC Operations supervisor must ensure that <u>all</u> persons (i.e., visitors, SWB employees) in the removal and staging work areas are aware that hazardous material/waste is being handled and that they act with integrity concerning its handling.

2.10 When handled properly and with adequate safety precautions as set out in these practices and procedures, the hazardous material/waste encountered in Telephone Company-owned equipment does not pose any danger to the persons involved. However, strict adherence to these practices and procedures on removal, storage and shipping of hazardous material/waste must be met in order to ensure the safety of the persons involved and of the environment.

- 2.11 Following is a list of the basic responsibilities of MARC Operations regarding hazardous material/waste:
 - o To search scrap for hazardous
 material/waste.

- o To separate hazardous material/waste by type of material.
- o To package hazardous material/waste according to DOT and Company regulations.
- o To complete the Bill of Lading (FASW 6152A) for hazardous material shipments and/or Manifest as required for hazardous waste shipments.
- o To sign the Bill of Lading or Manifest as originator.
- o To obtain the transporter's signature on the shipping document.
- o To mail the originator copy of the shipping document to Disposition Services Control Center (DSCC) located in St. Louis, Missouri.
- o To maintain a local file of all outbound hazardous material/waste shipments.

3. IDENTIFICATION OF HAZARDOUS MATERIAL/ WASTE

3.01 Under the EPA rules, the owner of waste is defined as a waste generator. With no exceptions, the generator is responsible for determining the constituents of their material/waste and, if hazardous, for assuring that it is disposed of properly.

3.02 To meet this requirement, all Company equipment that is designated for purposes other than reuse must be identified and, if necessary, searched for hazardous material/waste. This includes wet acid batteries, cold cathode tubes, beryllium oxide components, and units containing mercury and PCB's.

4. HAZARDOUS MATERIAL/WASTE

4.01 <u>Cold Cathode Tubes</u> - This section provides instructions to follow when identifying, handling, storing, packaging and shipping radioactive cold cathode tubes, i.e., Radium 226 Bromide and Krypton 85 type tubes.

- (a) Identification Radioactive tubes, in general, can be identified by the dark purplish color of the glass envelope. However, the 423 type tubes will have a clear glass envelope. Radium 226 Bromide tubes are generally, but not always, marked with a magenta three bladed radioactivity symbol printed on the exterior glass envelope. Some of the older tubes will not be marked with the radioactivity symbol but must be packaged according to the instructions for Radium 226 Bromide tubes. None of the Krypton 85 tubes are labeled with the three bladed radioactivity symbol. Figure 1 illustrates the various shapes and associated dimensions of radioactive tubes. The tube code numbers are located next to the illustration. Use of Figure 1 and Table A will help to identify Radium 226 Bromide and Krypton 85 tubes.
 - Radium 226 Bromide and Krypton 85 type cold cathode tubes are listed in Table A.
 - (2) Some older Radium 226 Bromide and Krypton 85 type cold cathode tubes have common tube code designations. This condition exists because when the new Krypton 85 type

tubes were first manufactured the code numbers assigned to the Radium 226 Bromide tube(s) being replaced were not changed. Table A can be used as a guide in the separation and identification of Radium 226 Bromide and Krypton 85 tubes. If the tube type cannot be determined, or if tubes are broken, they shall be considered 1.0 Microcurie Radium 226 Bromide for packaging and shipping purposes.

(b) Handling - During Central Office removals, when equipped frames are to be scrapped, all radioactive cold cathode tubes must be located and removed before the frame is dismantled or removed from its installed position.
However, should radioactive tubes be encountered at the MARC Center, the following procedures shall be followed.

- The small amount of radiation provided by the cold cathode
 tube will not cause overexposure
 during normal handling on the job.
 However, to reduce personal exposure
 to a minimum, casual unnecessary
 handling is prohibited.
- (2) When removing tubes from their installed positions, caution must be exercised to prevent them from falling and breaking. For hardwired tubes, two people are required for safe removal, i.e., one to support the tube on the equipment side of the frame while the second removes the wiring and mounting screws on the wiring side of the frame.
- (3) The MARC Operations supervisor must be notified anytime a

radioactive tube is broken. In the event the MARC Operations supervisor cannot be reached, the Assistant Manager-Hazardous Materials Removals in the Disposition Services Control Center (DSCC) shall be contacted on tel. #314-247-9920.

- (4) If a radioactive tube should break, walk out of the immediate area and wait a few minutes to prevent inhalation of expended dust and vapor before attempting to pick up broken parts.
- (5) In the case of any broken Radium 226 Bromide tubes, the MARC Operations supervisor in charge of the clean up procedures shall perform Geiger counter tests to ensure that all surface contamination has been removed.
- (6) Clean up procedures shall be followed as outlined in Attachment A.
- (7) For safety precautions to be used when handling cold cathode tubes, see Attachment B.
- (8) For hard wired tubes, all metal brackets and external leadsshall be removed before packaging.
- (c) Storage/Packaging The fragile nature of cold cathode tubes and the potential danger of radioactive material/waste contained therein demands caution and care throughout the storage/packaging process.
 - Cold cathode tubes are normally received at the MARC Center in

compartmented (egg carton type) fiberboard containers.

(2) Radium 226 and Krypton 85 tubes should be sorted by type for storage at the MARC Center. Fiberboard containers (R-4868A) should be ordered through the Local Purchasing Office (LPO) from:

- Protecta-Pac Systems 705 Pennsylvania Ave. - South Minneapolis, MN 55426 Tel: (612) 540-9500 or (800) 328-1784
- (3) Stacks of cold cathode tubes shall not be located within three (3) feet of fixed work areas.

(4) When sufficient quantities of tubes are on hand to fill a
fifty-five (55) gallon drum
(approximately 2000), the tubes should be transferred from the R4868A containers to a DOT approved 17H specification fifty-five (55) gallon drum.

(5) In order to reduce the surface radiation level of the drum, Radium 226 tubes should be placed in the center or core of the drum and Krypton 85 tubes shall be used to fill the drum. A ratio of 4:1 (Krypton:Radium) or greater should be utilized when packing tubes for disposal.

(6) Before placing tubes into a drum, a 2-3 inch layer of"bubble pack" or similiar packing materials should be placed into the bottom of the drum. As tubes are placed into the drum, the code designation on each tube must be checked and recorded in microcuries to determine the radioactive material content of the drum. After the drum is filled, a 2-3 inch layer of "bubble pack" packing material should be placed on top of the tubes. The drum should then be closed and a security seal affixed.

- (d) Shipping Certain measurements of radiation levels are required to properly mark, label and ship drums of radioactive tubes. The radiation activity rate for the tubes contained in each drum must be recorded on the shipping document.
 - (1) There are three radiation measurements that must be taken
 by the shipper which will be used in completing the shipping documentation. These are defined below.
 - <u>Radiation level</u> means the maximum radiation dose-equivalent rate at the shipping container's surface expressed in millerem per hour (mrem/h). For documentation purposes, the entire shipping container will have to be scanned using a Geiger counter to determine the maximum surface radiation level.
 - Transport index means the dimensionless number (rounded up to the first decimal place) placed on the label of a package to designate the degree of control to be exercised by the carrier during transport. The Transport Index is obtained by determining the maximum radiation level in millirem per

hour (mrem/h) at one meter (3.3 feet) from the external surface of the shipping container.

- o Wipe test means a procedure for determining the nonfixed (removable) radioactive contamination on the external surface of the shipping container. In no case can the nonfixed contamination on the external surface of the package exceed 2.2 disintegrations per minute (dpm) per square centimeter (.4 x .4 square inches). The level of non-fixed radioactive contamination is determined by wiping an area of 300 square centimeters (approximately $6-4/5" \ge 6-4/5"$) of the container's surface with an absorbent material, using moderate pressure. Sufficient measurements must be taken in the most appropriate locations to yield a representative assessment of the nonfixed contamination levels. Three such measurements should be sufficient to meet this need.
- (2) Instructions for labeling and final disposal of radioactive
 tubes may be obtained by contacting
 the Assistant Manager-Hazardous
 Materials Removal in the Disposition
 Services Control Center (DSCC) on
 tel. #314-247-9920 located in
 St. Louis, Missouri.

4.02 Units Containing Mercury - Mercury can be found in small amounts encapsulated in telephone equipment. Present scrap management practices require that mercury be purged from general scrap prior to disposition, and that subsequent disposition of the units containing mercury may be sold for reclamation. Mercury can be found in Telephone Company equipment in the form of liquid mercury filled relays and mercury vapor filled tubes.

(a) Identification

(1) Mercury relays have two basic configurations, i.e., circular based and rectangular based. They are sealed with a smooth metal casing and many, but not all, have the warning "DANGER HIGH PRESSURE - DO NOT OPEN" printed on the casing. Others will have arrows indicating the direction in which it is to be installed. The relays vary in size and shape and are classified according to relay codes printed on the metal casing. Refer to Figure 2 which provides pictorial drawings with dimensions of each of the coded relays. Some relays are identical in appearance. Tables B and C list equipment which contains mercury relays. Table D lists mercury relays and the amount of mercury in each type. Table E lists mercury switches and the amount of mercury in each switch. Mercury relays are most commonly found in Central Office Equipment, PBX's, Key Systems, Coin Telephones and Test Sets.

(2) Mercury vapor tubes are usually long and narrow, e.g., some 6" to 9.5" in length and all are very fragile. These tubes are most commonly found in central office equipment. To assist in the identification of mercury vapor tubes, refer to Figure 2A which includes pictorial drawings and tube dimensions. The tubes that have been manufacture discontinued are not illustrated in Figure 2A; however, they will be very similar in physical appearance. Table F lists mercury vapor tube codes and the amount of mercury vapor contained in each type.

(b) Handling

 Mercury Relays - Although mercury relays are not fragile, they shall not be treated harshly.
 The only dangerous condition that can arise is if a mercury relay should break causing liquid mercury leakage.
 Clean up procedures shall be followed as outlined in Attachment C. For safety precautions to be used when handling mercury relays, see Attachment D.

(a) Some mercury relays are plug-in type relays. These canbe removed by simply pulling the relay from its socket.

 (b) Other mercury relays have a soldered connection, such as those connected to circuit boards or packs. These relays should be removed from circuit boards by the use of desoldering equipment.

(c) Large quantities of securely packaged relays present no danger to personnel.

(2) Mercury Vapor Tubes - When handling mercury vapor tubes, caution must be exercised to prevent them from falling and breaking. Mercury vapor tubes, even when packaged shall not be located or stored in an unprotected area where damage could occur. If a tube should break when in a stored location or by dropping, walk away from the immediate area for a few minutes to prevent inhalation of concentrated mercury vapor before attempting to reenter the area to pick up broken pieces. Clean-up procedures shall be followed as outlined in Attachment E. For safety precautions to be used when handling mercury vapor tubes, see Attachment F. Contained and broken tubes with their bases still engaged in sockets shall be removed by using an Electron Tube Extractor. After use, the extractor shall be washed with soap and water.

(c) Storage/Packaging

(1) <u>Mercury relays</u> shall be packaged loosely in fiber drums with a capacity of fifteen (15) to twenty (20) gallons. Before placing relays into the drum, a heavy duty plastic liner should be inserted into the drum. After filling the drum, the plastic liner should be sealed with heavy duty tape. Any damaged relays should be double bagged to prevent mercury leakage.

- (2) Mercury vapor tubes should be individually wrapped with adequate cushioning material to prevent breakage. Wrapped tubes in a carton should be surrounded on all six sides by additional cushioning material. All cartons shall be sealed with pressure sensitive tape so as to prevent any mercury leakage.
- (d) Shipping Units containing mercury
 - All Mercury shipments shall be shipped by <u>overland</u> means of

transportation. Specification outside packaging will not be required. However, shipping containers must be marked "Mercury Relays, N.O.I." or "Mercury Tubes, N.O.I. (whichever is appropriate) so that the contents can be easily identified by the recipient.

(2) Mark each shipping container with the appropriate address of the location originating the shipment.

(3) Bills of lading should include an appropriate description of the material being shipped, e.g.:

"Mercury Relays, N.O.I."

(4) Instructions for labeling and final disposal of mercury units
may be obtained by contacting the
Assistant Manager-Hazardous Materials
Removal in the Disposition Services
Control Center (DSCC) on tel.
#314-247-9920 located in St. Louis,
Missouri.

4.03 Polychlorinated Biphenyls (PCB's) -

(a) Identification - Presently two types of components containing
PCB's have been identified, i.e.,
capacitors in telecommunication
equipment and ballasts found in some
older fluorescent, lighting fixtures.
PCB's contained in electrical products
are generally identified by company
trade names, however, such components
used in telecommunications equipment, by
majority, are not so identified. Some
ballasts found in fluorescent lighting
could include units which contain PCB's.
Dismantled fluorescent lighting ballasts must be inspected for labels affixed to the ballast identifying one of the following PCB names:

AROCLOR	HYVOL, J.
AROCLOR B	INTERTEEN
ASBESTOL	KENNECHLOR
ASKAREL (generic)	NO~FLAMOL
CHLOREXTOL	PHENOCOLOR
CLORINOL	PHRALENE
CLORPHEN	PHDRAUL
DIACHLOR	PYRANOL
DK	PYROCLOR
DYKANOL, A, F, G, L, XL	SAF-T-KUHL
ELEMEX	SANTOTHERM
EUCAREL	THERMINOL
FENCLOR	

(1) To assist in the location and identification of PCB
apparatus, refer to Tables G, H, I
and J, and Figure 3 which gives
pictorial drawings with dimensions
and descriptions of PCB capacitors
and condensers containing over three
(3) pounds of PCB's.

Most, but not all, PCB capacitors have the following characteristics:

High voltage (over 200 VDC) Square or oval in shape Plastic or porcelain insulators on the terminals

- On oval capacitors, a rubber boot or plastic caps covering the terminals
- <u>Table "G"</u> provides a listing of capacitors by manufacturer's designated code numbers, their PCB weight, and associated illustration figures.

SW 745-010-902

- <u>Table "H"</u> provides a listing of capacitors with over three pounds of PCB's.
- <u>Table "I"</u> provides a general listing of trade names which are known to be PCB types.
- <u>Table "J"</u> provides location information using associated SD and J drawings of equipment which contains PCB apparatus.

(2) PCB capacitors are generally used by the Telephone Company in rectifiers and power units found in central office equipment and PBX's.

- (3) Ballasts containing PCB's are most commonly found in fluorescent lighting units in coin telephone booths and central office frame mounted fixtures.
- (4) As of July 1, 1979, the manufacture and export of PCB's in the United States was forbidden.
- (5) Any capacitor that is labeled "ELECTROLYTIC" does not contain PCB's.
- (b) Handling When a component is suspected of containing PCB's and cannot be positively identified, it should be considered to contain PCB's and treated as such. Safety precautions as shown in Attachment H shall be used when handling items containing PCB's.
 Clean-up procedures shall be followed as outlined in Attachment G.
 - Generally, a rectifier or power supply must be removed from a

piece of equipment to gain access to the capacitors. Once a PCB capacitor has been located, it can be removed by cutting the leads.

WARNING: Due to potential high voltage found in many capacitors, make sure the PCB capacitor is discharged, prior to removal from equipment. The capacitor may be discharged by grounding the bare terminals to the frame with an insulated screwdriver.

- (2) Units containing PCB shall be separated from the other scrap and collected in 55 gallon steel drums meeting DOT 17H specifications.
- (3) Capacitors containing three (3) pounds or more of PCB per
 capacitor are regulated under the EPA
 Toxic Substances Control Act.
 Contact the Disposition Services
 Control Center (DSCC) located in
 St. Louis for instruction prior to
 dismantling equipment containing PCB
 type capacitors weighing ten or more
 pounds.

NOTE: Capacitors containing ten (10) or more pounds of PCBs cannot be held in storage longer than thirty (30) days.

(c) Storage/Packaging

(1) All PCB components shall be packed in an openhead, steel drum which meets DOT 17H specification or equivalent container. This is a common 18 gauge steel drum which can be obtained locally. However, DOT 17H specifications must be emphasized.

- (2) To prevent leakage from the drum, first insert a four (4)
 mill plastic liner into the drum, then place 2-3 inches of oil absorbent material into the drum.
 This can be ordered locally under trade names such as oil-dry, speedi-dry, sorbitol, safe-n-dry, zepposorb, absoran and oilsorb.
- (3) Drums should be packed as to prevent any leakage or shifting of material during shipment.
- (d) Shipping Instruction for labeling and final disposal of PCB's may be obtained by contacting the Assistant
 Manager-Hazardous Materials Removal in the Disposition Services Control Center (DSCC) on tel. #314-247-9920 located in St. Louis, Missouri.

4.04 <u>Batteries</u> - Under present guidelines, removal and shipping of central office batteries will be performed from the central office involved and will not be received at the MARC Center locations. Therefore, no procedures for the handling of central office batteries will be issued in this practice.

- Wet Cell Batteries For handling, packing, marking, and labeling of of lead-acid type batteries refer to BR 010-160-201. Final disposition procedures shall be coordinated with Disposition Services Control Center (DSCC) on tel. #314-247-9920 located in St. Louis, Missouri.
- (2) Other Types of Batteries -Ordinarily, small quantities of dry cell batteries may be discarded as trash. However, since most batteries contain chemicals, some of which may be

hazardous or toxic, when large numbers are discarded due to scrapping activities, end of shelf life, etc., questions related to proper disposal should be directed to the Disposition Services Control Center (DSCC) on tel. #314-274-9920 located in St. Louis.

NOTE: Other questions related to battery handling, shipping, and disposition should be directed to the Disposition Services Control Center (DSCC) located in St. Louis.

- 4.05 Beryllium Oxide
 - (a) Identification Beryllium Oxide (BeO) a white ceramic material may be found encased in telephone company microwave equipment. Two components, a Beryllium Oxide Electron Tube (416-C) and a Traveling Wave Guide Amplifier (TWGA) contain varying amounts of BeO. The small amount of BeO contained in this equipment is protected by a metal housing. However, the glass apparatus contained within the TWGA may become separated from the main housing. Extreme care should be taken when handling this fragile item.
 - (b) Handling Due to the highly toxic nature of BeO, utmost care should
 be exercised when handling components containing this material.

<u>Warning</u>: Beryllium oxide <u>dust</u> or <u>fumes</u> are highly toxic if inhaled, or if particles enter a cut or abrasion. Avoid handling the beryllium oxide ceramics; if they are touched, the hands must be washed before smoking or eating.

(c) Storage/Packaging - All beryllium components should be individually

SW 745-010-902

wrapped with cushioning material. Pack all wrapped tubes in the center of a sturdy, sealable, cardboard container surrounded on all sides with cushioning material. All cartons shall be sealed with pressure sensitive tape.

(d) Shipping - Instructions for labeling and final disposition of beryllium oxide components may be obtained by contacting the Assistant Manager-Hazardous Materials Removal in the Disposition Services Control Center (DSCC) on tel. #314-274-9920 located in St. Louis, Missouri.

5.0 TRAINING

5.01 All MARC Center employees who handle hazardous materials/wastes shall be provided classroom or on-the-job training that teaches them the proper management of hazardous materials/wastes to ensure the MARC Center's compliance with all applicable rules and regulations.

5.02 The training shall be provided by the Asst. Mgr.-Hazardous Materials Removal or another individual who has knowledge of the characteristics of the hazardous materials/wastes stored at the MARC Center and the proper management of such materials.

- 5.03 The training shall include the following:
 - (a) A description of the hazardous materials/wastes and the hazards associated with those materials.
 - (b) A description of the proper management of these materials, such as proper containers and storage practices.

5.04 Employees shall take part in an annual review of their original training.

- 5.05 The following records shall be retained:
 - (a) The job title and description of each position at the location relating to hazardous material/waste management.
 - (b) The name of the employee filling each position and the employee's qualifications.
 - (c) A description of the type and amount of initial and continuing training that will be given to each position.
 - (d) Documentation that each employee has received the required training or experience.
 - (e) Training records of current personnel shall be retained until closure. Records for former employees shall be retained for 3 years from the date of the employee's departure.

6.0 CONTINGENCY PLAN

6.01 All MARC Centers that accumulate, handle or store hazardous material/ waste shall develop a contingency plan for the protection of human health and the environment from fires, explosions, or releases of hazardous material/waste.

6.02 The MARC Operations supervisor and the Supv.-Removal Services should act as joint Emergency Coordinators.

6.03 At a minimum the plan must include:

 (a) A list of local emergency response teams including the telephone
 numbers of local Police, Fire
 Department, Hospitals, doctors and other
 emergency response teams.

- (b) Plan of action to minimize the possibility of the incident spreading or recurring, i.e., stopping operations, containing released material and posting "off limits".
- (c) An evacuation plan, including signals, main evacuation routes and alternate routes.
- 6.04 A copy of the contingency plan shall be maintained at the facility and be available for emergency response teams.

6.05 When there is an imminent or actual emergency situation, the Emergency Coordinator(s) should:

- (a) Evacuate the area and post "Off Limits".
- (b) In case of fire, notify local Fire Department.
- (c) Contact their immediate supervisor and be prepared to identify the character, source, amount and extent of the released materials. Also assess the hazards, both direct and indirect, to human health and the environment.
- (d) Report the incident as soon as reasonable to the Disposition
 Services Control Center (DSCC) located
 in St. Louis on tel. # 314-247-9920.
- 6.06 Following the incident, the Emergency Coordinator should contact

the Disposition Services Control Center (DSCC) located in St. Louis on tel. # 314-247-9920 for assistance in clean-up, storage and disposal of the hazardous material/waste, contaminated soil, water or other debris resulting from the incident.

6.07 The Assistant Manager-Hazardous Material Removals is the contingency and emergency plan coordinator in the DSCC. This coordinator will assist in the preparation of these plans and will notify the company environmental specialist as required and will represent the DSCC in meeting with federal and state environmental representatives.

6.08 MARC Center contingency plans must be developed in concert with the local MARC Center contract. The MARC Center contract states, under the Emergency clause; "Buyer (the contractor) shall develop, prepare and be capable of implementing emergency plans in the event of a hazardous material/waste discharge". Based on this clause all MARC Center contingency plans will include references to the contractor's emergency response plan.

7.0 GLOSSARY

7.01 This glossary contains a list of environmental acronyms and other terms related to hazardous material/waste management.

- 7.02 ACRONYMS
- ACGIH American Conference of Governmental and Industrial Hygienists
- AEA Atomic Energy Act
- ANPR Advanced Notice of Proposed Rulemaking

- APA Administrative Procedures Act
- ASTM American Society of Testing & Materials
- BAT Best Available Technology
- BLM Bureau of Land Management
- BPT Best Practicable Technology
- CAA Clean Air Act
- CAB Civil Aeronautics Board
- CAS# Chemical Abstract Service Number
- CDC Center for Disease Control
- CERCLA Comprehensive Environmental Response, Compensation, and Liability Act (Superfund)
- CEQ Council on Environmental Quality
- CFC Chlorofluorocarbons
- CFR Code of Federal Regulations
- CGA Compressed Gas Association
- CPSA Consumer Product Safety Act
- CPSC Consumer Product Safety Commission
- CWA Clean Water Act
- DOC Department of Commerce
- DOD Department of Defense
- DOE Department of Energy
- DOI Department of the Interior

- DOT Department of Transportation
- EIS Environmental Impact Statement
- EPA Environmental Protection Agency
- FAA Federal Aviation Administration
- FDA Food and Drug Administration
- FFDCA Federal Food, Drug and Cosmetics Act
- FHA Federal Highway Administration
- FHSA Federal Hazardous Substances Act
- FIFRA Federal Insecticide, Fungicide and Rodenticide Act
- FR Federal Register
- FWPCA Federal Water Pollution Control Act
- HMT Hazardous Materials Table
- HMTA Hazardous Materials Transportation Act
- IARC International Agency for Research on Cancer
- IATA International Air Transport Association
- ICAO International Civil Aviation Organization
- ICC Interstate Commerce Commission
- IMDG International Maritime and Dangerous
 Goods (Code)
- IMO International Maritime Organization

- IUPAC International Union of Pure and Applied Chemistry
- LD₅₀ Lethal Dose, 50%
- LC₅₀ Lethal Concentration 50%
- MARC Material Reprocessing and Consolidation
- MDC Material Distribution Center
- MRPSA Marine Research, Protection and Sanctuaries Act
- MSC Maritime Safety Commission
- MSDS Material Safety Data Sheet
- MTB Material Transportation Board
- NAAQS National Ambient Air Quality Standards
- NACE National Association of Corrosion Engineers
- NAS National Academy of Sciences
- NBS National Bureau of Standards
- NCI National Cancer Institute
- NEPA National Environmental Policy Act
- NESHAPS National Emissions Standards for Hazardous Air Pollutants
- NFPA National Fire Protection Association
- NIH National Institute of Health
- NIOSH National Institute on Occupational Safety and Health

- NOAA National Oceanic and Atmospheric Administration
- NOI Not Otherwise Indexed
- NOIBN Not Otherwise Indexed by Name
- NOS Not Otherwise Specified
- NPDES National Pollutant Discharge Elimination System
- NRC Non-reusable Container
- NRC Nuclear Regulatory Commission
- NSPS New Source Pollution Standards
- NTP National Toxicology Program
- OMB Office of Management and Budget
- ORM Other Regulated Material
- OSHA Occupational Safety and Health Act
- OSHA Occupational Safety and Health Administration
- OSM Office of Surface Management
- PCB Polychlorinated Biphenyl
- PMN Pre-Manufacture Notification
- POTW Publicly Owned Treatment Works
- PPB Parts Per Billion
- PPM Parts Per Million
- RCRA Resource Conservation and Recovery Act

```
SW 745-010-902
```

- RPAR Rebuttable Presumptions Against Registration
- RQ Reportable Quantities
- RSPA Research and Special Programs Administration
- RTECS Registry of Toxic Effects of Chemical Substances
- SDWA Safe Drinking Water Act
- SEC Securities and Exchange Commission
- SIC Standard Industrial Classification
- SIP's State Implementation Plans
- SPCC Spill Prevention Control and Countermeasure (Plan)
- STS Single Trip Container
- STCC Standard Transportation Commodity Code
- STEL Standard Term Exposure Limit
- TCS Telephone Company Storeroom
- TLV Threshold Limit Value
- TSA Transportation Safety Act
- TSCA Toxic Substances Control Act
- TSD Treatment, Storage or Disposal
- TSDF Treatment, Storage or Disposal Facility
- TWA Time Weighted Average

- USDA United States Department of Agriculture
- USGA United States Geological Survey
- 7.03 Terms

CAPACITOR

A devise which stores electrical charges. Usually consists of two or more opposed conducting plates separated by thin layers of a non-conducting material.

COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION, AND LIABILITY ACT OF 1980 (also known as "superfund")

This act authorizes the EPA to administer funds allocated to cleanup hazardous substance releases from designated sites. Additionally, Congress also gave the EPA authority to recover from responsible parties, when identified, the costs incurred for cleanup activities.

CIRCUIT PACK

A small plug-in unit in the form of a printed wiring board used for mounting components such as capacitors, inductors, diodes, resistors, transistors, etc., which are interconnected to perform one or more circuit functions such as amplification, gating, timing, etc.

COMBUSTIBLE LIQUID

Any liquid with a flash point at or above 100°F and below 200°F and does not meet any other hazard class definition.

CORROSIVE MATERIAL

Any liquid or solid that causes visible destruction of human skin or a severe corrosion to steel.

DISPOSAL FACILITY

A facility or part of a facility at which hazardous waste is intentionally placed into or on the land or water, and at which the waste will remain after closure.

FLAMMABLE SOLID

Any solid likely to ignite easily through friction, retained manufacturing or processing heat or other means. Does not include explosives.

GENERATOR

Any person or facility, by site, that produces more than 1,000 kilograms (2,200 pounds) of hazardous wastes in a calendar month or accumulates that amount on-site at any one time.

HAZARDOUS CHEMICAL SUBSTANCES AND MIXTURES

Substances and mixtures which are regulated under TSCA in manufacturing, processing, distribution in commerce, use or disposal because it poses or will present an unreasonable risk of injury to health or the environment.

HAZARDOUS MATERIAL

Substances or materials which have been determined to be capable of posing an unreasonable risk to health, safety and property when transported in commerce.

HAZARDOUS MATERIAL SURVEY

A survey of equipment to be scrapped which provides for the identification, removal, staging and proper disposal of all material classified as hazardous by the EPA. This survey must be performed by qualified BOC personnel or contracted with an equally qualified Vendor prior to the removal of scrap.

HAZARDOUS SUBSTANCE

Includes items that are listed under the following environmental laws: (1) hazardous wastes regulated under the Resource Conservation and Recovery Act; (2) hazardous air pollutants regulated under the Clean Air Act; (3) water pollutants regulated under the Clean Water Act; and (4) hazardous chemical substances and mixtures regulated under TSCA.

HAZARDOUS SUBSTANCE RELEASE

Any spill, leaking, pouring, emitting, emptying, discharging, injecting, escaping, leaching, dumping, or disposing of a hazardous substance into the environment.

HAZARDOUS WASTE

Wastes that have been identified as possibly causing or contributing to serious illness or death or that pose a substantial threat to human health or the environment if managed improperly. Hazardous wastes include (1) items that are listed in the federal rules, and (2) wastes that are not listed but exhibit one or more of the characteristics of a hazardous waste; i.e., ignitable, corrosive, reactive or toxic. SW 745-010-902

HAZARDOUS WASTE MANIFEST

A shipping document required for shipments of regulated quantities of hazardous wastes.

IRRITATING MATERIAL

A liquid or solid that, upon contact with fire or exposure to air, gives off dangerous or intensely irritating fumes. Does not include any Class A poison.

ORM-A

A material with anesthetic, irritating, noxious, toxic or similar property and which can cause annoyance or discomfort to passengers and crews in the event of a leak during transport.

ORM-B

Materials, including solids when wet, that can damage transport vehicles or vessels if leaked. Included are materials that corrode aluminum. (Mercury)

ORM-C

Materials with characteristics that make them unsuitable for transport unless properly managed. (Asbestos)

ORM-D

Materials, such as consumer commodities, that have properties that would classify in another hazard class but whose form, quantity and packaging presents a limited hazard.

ORM-E

RCRA hazardous wastes and CWA hazardous substances that do not meet the definition of any other hazard class. (PCB's)

RADIOACTIVE MATERIAL

Any material or combination of materials that emits ionizing radiation and has a specific activity in excess of 0.002 microcuries per gram.

RESISTOR

A device made of metal, carbon or other substance used to restrict or control the flow of electrical current.

RESOURCE CONSERVATION AND RECOVERY ACT (RCRA) OF 1976

RCRA authorized the EPA to develop a system for regulating the management of hazardous wastes. These rules, known as the "Hazardous Waste Management System", became effective November 19, 1980.

SHIPPING PAPER

May be a shipping order, bill of lading, hazardous waste manifest, or other shipping document serving a similar purpose containing the information as required by the DOT.

SMALL QUANTITY GENERATOR

An individual facility that generates less than 1,000 kilograms (2,200 pounds) of hazardous waste in a calendar month or accumulates on-site less that that amount at any one time.

STORAGE FACILITY

The holding of hazardous waste for a temporary period, at the end of which the hazardous waste is treated, disposed of or stored elsewhere.

TOXIC SUBSTANCES CONTROL ACT (TSCA) OF 1976

This act authorized the EPA to obtain production and test data from industry on selective chemical substances and mixtures and to regulate the substances when determined that they pose an unreasonable risk to human health or the environment. As a result of this act, the EPA developed the existing regulation on polychlorinated biphenyls (PCB's), titled "Polychlorinated Biphenyls: Manufacturing, Processing, Distribution in Commerce, and Use Prohibitions."

TRANSISTOR

A tiny, efficient amplifying device that performs many of the functions of the vacuum tube. Consists of a small block of semiconductor, usually germanium, that has at least three electrodes. Has made possible the miniaturization of telephone and electronic apparatus.

TRANSPORTATION SAFETY ACT (TSA)

Although laws covering the transportation of hazardous materials date back from the late 1800's, this act was passed by Congress in 1974 and extends the DOT's authority to regulate hazardous materials, including regulated hazardous wastes and hazardous substances, when offered for shipment over public roadways. The Materials Transportation Bureau within the DOT is responsible for the continuing administration of the existing rules entitled, "Hazardous Materials Regulations".

TREATMENT FACILITY

A facility utilizing any method, technique or process to change the physical, chemical or biological character or composition of the hazardous waste so as to neutralize the waste, recover energy or material resources from the waste, render it non-hazardous, or less hazardous for purposes of transporting, storing or disposal; or amenable for recovery or storage, or reduced in volume.

	Attachment A Page 1 of 1
	CLEAN-UP PROCEDURES - COLD CATHODE TUBES
1.	Employees who have cuts, abrasions or open sores on exposed parts of the body, particularly the hands, shall not handle broken parts from radioactive tubes.
2.	Prior to picking up broken parts of radioactive tubes, employees shall wear a pair of Cotton Gloves.
3.	Safety glasses shall be worn during clean-up procedures.
4.	Employees who cut themselves in the process of handling broken parts of radioactive tubes shall immediately wash the cuts in warm water with mild soap. Rinse thoroughly. Repeat the above procedure three times. Report the injury to the job supervisor.
5.	Using rigid pieces of paper, pick up the broken tube pieces and place them in the center of a suitably-sized rag. Fold and place the rigid pieces of paper on top of the broken parts, then tie each pair of diagonal ends securely to form a compact bundle.
6.	Clean the affected floor area with a second, larger damp cloth. When finished, spread the cloth out on the floor so that the contaminated side is facing upward. Place bundle of broken tube pieces in the center, place gloves on top of bundle, tie each pair of diagonal ends of the cloth securely to form a compact bundle.
7.	Place the bundle in a suitably-sized plastic bag obtained locally and seal closed with pressure sensitive tape. Place the bundle in an appropriately-sized shipping carton and seal securely with pressure sensitive tape or 3" wide tape. Final disposition of these materials will be the same as cold cathode tubes.
8.	Do not use vacuum cleaners or brooms to pick up broken parts of radioactive tubes.
9.	Do not dispose of broken parts of radioactive tubes through common rubbish removal service.
.0.	If there is an accidental breakage of ten (10) or more radioactive tubes at one location, the immediate area shall be covered with sheet material such as plastic or canvas to prevent radioactive dust and glass particles from spreading. The area shall be posted "OFF LIMITS" to alert all personnel and to ensure that the hazardous materials do not spread. For assistance in proper clean-up procedures, contact the Asst. MgrHazardous Material Removals in the Disposition Services Control Center (DSCC) located in St. Louis, Missouri on 314-247-9920.
1.	After clean-up procedures have been performed, the supervisor in charge shall perform Geiger counter tests to ensure that all surface contamination has been removed.
2.	Wash bands thoroughly with soap and water upon completion of any

ATTACHMENT B

	Attachment B
	SAFETY PRECAUTIONS - COLD CATHODE TUBES
1.	No food, drink, or smoking should be permitted when radioactive cold cathode tubes are being handled. Wash hands thoroughly with water and mild soap before eating, drinking, or smoking.
2.	The slight amount of radiation produced by the cold cathode tubes will not cause overexposure during normal handling on the job. However, to contain the level of personal exposure to a minimum, the practice of carrying spare tubes in clothing and casual unnecessary handling is prohibited.
3.	It is recommended that cold cathode tubes be handled and packaged by a small number of trained individuals.
4.	Stack(s) of radioactive cold cathode tubes shall not be located within three feet of fixed work location.
5.	Photographic film shall not be stored within fifteen feet of any concentrated source of radioactivity.
6.	Cartons of radioactive type cold cathode tubes stacked on the floor for temporary storage shall be protected from accidental damage by placing an appropriately sized sheet of plywood, masonite, or other similar structural material on top of the stack to prevent tube breakage.
7.	Because floor materials can become contaminated if Radium Bromide tubes are dropped and broken, it is recommended that a temporary floor covering (paper or other material) be spread in work areas prior to removal.
8.	If a radioactive tube(s) should break, walk out of the immediate area and wait a few minutes to prevent inhalation of expended dust or vapors before attempting to pick up broken parts. <u>DO NOT WALK ON PIECES OF</u> <u>BROKEN GLASS</u> . Follow instructions as indicated under Attachment "A".

ATTACHMENT C



ł.

ATTACHMENT D

	Attachment D
	SAFETY PRECAUTIONS - MERCURY RELAYS
1.	The liquid mercury in the relay becomes a safety handling problem should the casing break and leak.
2.	Liquid mercury is poisonous and under no circumstances shall it come in contact with the skin, eyes or internal parts of the body.
3.	No food, drinking, or smoking shall be permitted in areas where mercury relays are being handled.
4.	Employees shall wear safety eyeglasses for minimum eye protection. If necessary the Chemical Safety Goggles shall be worn when a Mercury Relays(s) are leaking from above eye level. Employees shall wear the Acid Resistant Gloves to prevent mercury contact with the hands.
5.	Although Mercury Relays are air-tight and are highly resistant to damage to cause leakage, caution shall be exercised to prevent physical damage.
6.	Large quantities of securely packaged Mercury Relays present no danger to personnel.
7.	The only condition that can arise is if a Mercury Relay(s) should break in a manner which causes liquid mercury leakage. All loose mercury shall be cleaned up immediately. See clean-up procedures as shown in Attachment "C".

 CLEAN-UP PROCEDURES - MERCURY VAPOR TUBES Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle broken mercury vapor tubes. Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag's fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed throughly with soap and lukewarm water and rinsed. Report the injury to the ob Supervisor. 	 CLEAN-UP PROCEDURES - MERCURY VAPOR TUBES Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle broken mercury vapor tubes. Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being pointubes. Mercury tapor tubes of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the pieces of rigid paper on the rag, wrap and tie the cards signanal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Mach hands throughly with soap and water upon completion of clean-up. Mach hands throughly with soap and water upon completion of clean-up. Shong hands throughly with soap and water and rinsed. Report the injury to a pair of fiele (b) minutes. The wound and hands shall be washed the of broken fiele of the diagonal be washed the of broken pieces of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (b) minutes. The wound and hands shall be washed the of booken by the soap and lukewarm water and rinsed. Report the injury to be supervisor. 		Attachment H
 Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle broken mercury vapor tubes. Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle broken mercury vapor tubes. Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Mash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hand shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 		CLEAN-UP PROCEDURES - MERCURY VAPOR TUBES
 Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Safety eyeglasses or chemical safety goggles must be worn. Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) mintes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	1.	Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle broken mercury vapor tubes.
 Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service. Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	2.	Safety eyeglasses or chemical safety goggles must be worn.
 Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes. Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	3.	Mercury Vapor Tubes shall never be disposed of through a common rubbish removal service.
 Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves. With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	4.	Do not use vacuum cleaners or brooms to pick up broken parts of Mercury Vapor Tubes.
 With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely. Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	5.	Mercury residue may be present on broken tube parts. Mercury, being poisonous, should not come in contact with the skin. Under no circumstances shall a broken tube be touched with bare hands. Prior to picking up broken parts of Mercury Vapor Tubes put on a pair of Acid Resistant Gloves.
 Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward. Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	6.	With a rigid piece of paper, place the broken pieces on a suitably sized rag. Fold and place the piece of rigid paper on the rag, wrap and tie the rag's diagonal ends securely.
 Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely. Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	7.	Clean the affected floor area with a second larger damp cloth. When finished, spread it out so that the contaminated side is facing upward.
 Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes. Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	8.	Place the bundle of broken pieces in the center and tie each pair of the diagonal ends of the cloth securely.
 Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	 Wash hands thoroughly with soap and water upon completion of clean-up procedures. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor. 	9.	Place this larger bundle in an adequately large plastic bag and seal with Tape. This bag will then be packed and shipped with mercury vapor tubes.
11. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor.	11. Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor.	10.	Wash hands thoroughly with soap and water upon completion of clean-up procedures.
		11.	Employees who cut themselves in the process of handling broken parts of mercury vapor tubes shall immediately rinse the cut(s) in cold water for a minimum of five (5) minutes. The wound and hands shall be washed thoroughly with soap and lukewarm water and rinsed. Report the injury to the Job Supervisor.

ļ

ATTACHMENT F

	Attachment F
	SAFETY PRECAUTIONS - MERCURY VAPOR TUBES
1.	Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle mercury vapor tubes.
2.	When handling, installing, or removing Mercury Vapor Tubes, caution must be exercised to prevent them from falling and breaking.
3.	No food, drinking, or smoking shall be permitted in areas where mercury vapor tubes are being handled.
4.	Employees shall wear safety eyeglasses for minimum eye protection. Chemical Safety Goggles should be work when Mercury Vapor Tubes are handled, installed, or removed at or above eye level.
5.	Mercury Vapor Tubes, even when packaged, shall not be located or stored in an unprotected area where damage could occur.
6.	If Mercury Vapor Tubes break when in a stored location or by dropping, walk away from the immediate area for a few minutes to reduce the possibility of any concentrated mercury vapor before attempting to reenter the area to pick-up broken pieces. Follow clean-up procedures as outlined in Attachment "E".
7.	Note: Mercury is highly corrosive with respect to aluminum. Do not put tubes or broken pieces in aluminum containers.

ATTACHMENT G

 CLEAN-UP PROCEDURES - POLYCHLORINATED BIPHENYLS (PCB'S) Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle PCB parts suspected of leakage. Safety glasses or chemical safety goggles shall be worn during clean-up procedures. Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors may cause possible respiratory problems, therefore, confined spaces must be ventilated. Acid resistant gloves shall be worn. Under no circumstances will leaking components be touched with bare hands. Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 		
 Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle PCB parts suspected of leakage. Safety glasses or chemical safety goggles shall be worn during clean-up procedures. Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors must be ventilated. Acid resistant gloves shall be worn. Under no circumstances will leaking components be touched with bare hands. Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amay's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. CAUTION: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 		CLEAN-UP PROCEDURES - POLYCHLORINATED BIPHENYLS (PCB'S)
 Safety glasses or chemical safety goggles shall be worn during clean-up procedures. Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors may cause possible respiratory problems, therefore, confined spaces must be ventilated. Acid resistant gloves shall be worn. Under no circumstances will leaking components be touched with bare hands. Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	1.	Employees who have cuts, abrasions, or open sores on exposed parts of the body, particularly the hands, shall not handle PCB parts suspected of leakage.
 Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors may cause possible respiratory problems, therefore, confined spaces must be ventilated. Acid resistant gloves shall be worn. Under no circumstances will leaking components be touched with bare hands. Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	2.	Safety glasses or chemical safety goggles shall be worn during clean-up procedures.
 Acid resistant gloves shall be worn. Under <u>no</u> circumstances will leaking components be touched with bare hands. Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	3.	Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors may cause possible respiratory problems, therefore, confined spaces must be ventilated.
 Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth. <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	4.	Acid resistant gloves shall be worn. Under <u>no</u> circumstances will leaking components be touched with bare hands.
 <u>CAUTION</u>: Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin. Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	5.	Liquid PCB spills should be cleaned up by using rags and/or other absorbent materials. The residual PCB's should be removed by using a petroleum solvent, such as Amway's Industrial Cleaner or other non-flammable type petroleum solvents. Use the solvent sparingly on a cloth.
 Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	6.	<u>CAUTION</u> : Solvents are highly flammable and shall be kept away from heat and sparks. Also, avoid prolonged breathing or repeated contact with skin.
 8. If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor. 9. Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	7.	Contaminated rags, gloves, and absorbent materials shall be placed into a plastic bag and stored in a 55 gallon steel drum. Final disposition of these materials will be the same as PCB type capacitors.
 Wash hands thoroughly with warm water and soap upon completion of clean-up procedures. 	8.	If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Report the injury to the Job Supervisor.
	9.	Wash hands thoroughly with warm water and soap upon completion of clean-up procedures.

l,

ATTACHMENT H

	Attachment
	SAFETY PRECAUTIONS - POLYCHLORINATED BIPHENYLS (PCB'S)
1.	No food, drinking, or smoking shall be permitted in areas where PCB items are being handled or stored.
2.	Exposure to low concentrations of PCB's may cause long term toxic effects in many living organisms.
3.	Safety glasses shall be worn when a PCB type capacitor or ballast is to be removed from equipment.
4.	Acid resistant gloves shall be worn when handling PCB components or when cleaning-up any PCB spillage.
5.	<u>WARNING</u> : Due to high voltage found in many capacitors, make sure the capacitor is discharged prior to removal from equipment. The capacitor may be discharged by grounding the terminals to the frame with an insulated screwdriver.
6.	Small spills from capacitors or ballasts seldom cause any respiratory problems; however, when leaking PCB's come in contact with a heat source, the PCB material may vaporize. Inhalation of these vapors may cause possible respiratory problems, therefore, confined spaces must be ventilated.
7.	If PCB's should get into the eyes, they should be irrigated with water for at least fifteen minutes. Further, if PCB's enter an open wound or abrasion, the area shall be cleaned with soap and water at least three times. Contact the Job Supervisor immediately.
8.	Follow clean-up procedures as outlined in Attachment "G".
9.	Wash hands thoroughly with warm water and soap after handling any PCB item.



ł

		EXHIBIT 1 Page 2 of 5
	1.4	Another substance, polychlorinated biphenyls (PCB's), is covered by separate rules promulgated by the EPA on July 2, 1979 under the Toxic Substances Control Act (TSCA). This chemical is also subject to the DOT rules relating to transportation. PCB's can be found in some telephone equipment capacitors used by the Company.
	1.5	Under the EPA's rules on Hazardous Waste Management, hazardous waste is defined as an item which is removed from service for which it was initially intended and is by nature either toxic, ignitable, reactive, or corrosive.
	1.6	Hazardous wastes generated in a product or raw storage tank, a product or raw material transport vehicle, a product or raw material pipeline or in a manufacturing process unit are exempt from certain regulations. According to the rules, hazardous wastes generated in this manner do not become regulated until it exits the unit in which it was generated.
	1.7	Hazardous wastes (e.g., mercury, electrolyte and sludge) are regulated by the EPA when an aggregate weight of 2,200 pounds is generated during a calendar month at a location and will not be reused, reclaimed or recycled. Before a generator of regulated hazardous wastes can ship the wastes off-site, they are required to obtain an EPA Generator Identification Number for the location, utilize transporters and treatment/storage/disposal facilities that have EPA Identification Numbers applicable to their respective operations, and prepare a special shipping document, known as a hazardous waste manifest.
	1.8	In addition to the EPA's rules, Congress has specifically addressed the responsibilities of generators in two pieces of legislation. Under the framework contained in Subtitle C of RCRA, generators are given "cradle to grave" responsibility for ensuring that hazardous wastes are handled, transported and disposed of in an environmentally-sound manner. Also, the Comprehensive Environmental Response Compensation and Liability Act (CERCLA) of 1980 authorized the government to apportion the cost of cleaning up hazardous waste pollutants released from disposal or reclamation sites to the generators. Consequently, the Company must do everything possible to minimize the risk relative to the handling of hazardous materials/wastes generated from the Company-owned equipment.
11.	DISP	OSITION OF EQUIPMENT
	2.0	The following information outlines the present procedures used for removing telephone company equipment from service for purposes other than reuse that contains hazardous materials/wastes as outlined in paragraphs 1.3 and 1.4.



		EXHIBIT 1 Page 4 of 5
	ſ	POLYCHI OPINATED BIDHENVI S (PCR'S)
	2.6	As mentioned in paragraph 1.4, PCB's can be found in telephone equipment capacitors, the preponderance of which contain less than 1.36 kilograms (kg.) of dielectric. Small PCB capacitors, defined by the EPA as those containing less than 1.36 kg. (three pounds) of dielectric, can be disposed of as municipal solid waste.
	2.7	According to existing Company practices, PCB capacitors are segregated from the general scrap prior to removal. These capacitors should be collected and disposed of by EPA approved incinerator.
	2.08	Also, by EPA definition, a fluorescent light ballast is a small capacitor. Therefore, fluorescent light ballasts containing PCB's, which are taken out of service as part of a central office removal, should be collected and placed with the other PCB capacitors in preparation for incineration.
	2.09	Company guidelines on PCB's contained in transformers and other equipment related to Support Services' operations (i.e., buildings, automotive) are covered in Environmental Planning Guideline Number 1, a copy of which is on file in the State Environmental Coordinator's office.
	D.	COLD CATHODE TUBES
	2.10	There are two types of radioactive cold cathode tubes: (1) radium bromide tubes contain radioactive materials, and (2) krypton tubes are filled with radioactive gas. These tubes are not subject to the EPA rules; however, they must be packaged and transported in accordance with federal DOT rules. At present, these units are being accumulated at MARC (Material Reprocessing and Consolidation) Center locations, for later transportation and disposal at storage sites licensed by the Nuclear Regulatory Commission.
II.	COMP	ANY POLICIES AND PROCEDURES UNDER FEDERAL-STATE RULES
	3.0	The Company will obtain Generator Identification Numbers and manifest electrolyte generated from equipment removals where the hazardous waste is removed for purposes other than reuse or is not rendered harmless by elementary neutralization prior to shipment and is generated in a sufficient quantity as defined by the federal and state laws on this matter.
	3.1	Although PCB's are covered by TSCA, most states regulate the disposal of PCB's within their borders under their hazardous waste management laws. Consequently, the Company must comply with the same requirements as outlined in paragraph 3.0 for obtaining Generator Identification Numbers and manifesting PCB capacitors being shipped for incineration.

EXHIBIT 1 Page 5 of 5 3.2 As the MARC Center are the Company accumulation points for PCB capacitors prior to disposal, EPA Generator Identification Numbers have been obtained for these locations. Furthermore, each MARC Center location has a supervisor that has been designated with the responsibility for hazardous waste management. Based on information supplied by the Environment organization in the Support Services organization, the hazardous waste supervisor will review each removal and evaluate the need for obtaining EPA Identification Numbers file and obtain the numbers, where appropriate and retain copies of the hazardous waste manifest for three years as required under the rules. Β. TRANSPORTATION REQUIREMENTS 3.3 A universal manifest document will be used on shipments of regulated hazardous wastes where no requirements exist for using a state form. On shipments of unregulated hazardous materials and wastes, the standard bill of lading form will be used for record-keeping purposes. In both cases, copies of this documentation will be retained by the MARC Center hazardous waste supervisor for a minimum of three years.

	Southwestern Bell Telephone		R	ETURN	ED MATE!	RIAL I	NOTICE						FA FORM SW (REV 6.8)	5 38 1b
)					PAC BOXES	KED IN	4			5. 2	N.N.			
	SW 745-011-901; SW 745-010-901; SW 790-100-540				BUNDLES - CARTONS -			TRAN	4SPORTATION DUNT			PAGE	0F	
RETUR	NED				COILS -			DATE	PED		CARRIL	ER		
FROM	TITLE	STREET A	NDRESS		REELS - OTHER -			INST	ALLING ER NO.			S S S S S S S S	ETS ADDED BY	
	CITY STATE	ZIP CC	ĢE					01110			ESPONSIBIL	ITY COD	F - CHARGED	Γ
	RESPONSIBILITY CODE - ORIG.	DCATION C	- :00E		EC		CPR (ACCT.	FA ONLY)						
				-					OR EMPLOYE	E PREPARIN	IG FORM	ш. 	OR ACCTG. USE	NLY
PREL.	USE OF EMPLOYEE FREE PRIMA OF THE MAN OF ITEM	* COND.	QUANTIT	CONTR.	PRICE	UNIT	AMOUNT	FUNC./ACCI CODE TO BI CREDITED	E ORDER NO./ EST. NO./	D UNDER ACCT CODE	122- 01	YEAR LACED IN 100.1		
		-												
									-					
		-							YES-HAZA	RDOUS N	ATERIA	LS HAV	ы	
						+			BEEN	PURGEI				
									NO-HAZAR HAVE	DOUS M/ NOT BEE	ATERIAL: EN PURGI	S, IF ED.	ANY,	
														T
												+		
		_		_ ≚: _		IS REP.	ORTED WHEN	RECOVER RECOVER						
	TEL NO.			z										
ORIG	INATOR: (TITLE) TEI NO		DATE						RECEIV	ED BY:				ATE
SIGN	IED: TITLE) TEL NO		DATE					RECEIVE	 ZD					
APP	ROVED: (TITLE)		DATE	1		5]		CLASSI	IAL FIED BY:				ATE
							THE ITEMS							
Idna	LICATE ADMINISTRATIVE RETENTION ONLY			TUBER	-UKWARDED									

EXHIBIT 2

Page 33

TABLE A

					TABL	EA lof2
					ruge	1 01 2
		00	LD CATHODE	TUBE HART		
	RADIUM BRO	MIDE TUBES		KRYPTON	I TUBES	
	RADIUM 22	6 CONTENTS	DATE CONVERTED	KRYPTON 8	5 CONTENT	CODE M.D.
TUBE CODE	MICROCURIES	MILLICURIES	T0 KR-85	MICROCURIES	MILLICURIES	REPLACED BY
2124	0 10	0.0001			······································	2120
313A 313D	0.10	0.0001	-	-	-	3130
3138	0.10	0.0001	-	-	-	313CA
21200	0.01	0.00001	6026	0.50	0.0005	21204
313CA	0.10	0.0001	6026	0 50	0 0005	31304
31308	0.01	0.00001	6026	0.50	0.0005	_
31300	0.01	0.00001	6026	0.50	0.0005	
21200	0.01	0.00001	6020	0.50	0.0005	_
3330	0.01	0.00001	-	0.50	0.0005	1261
3464	0.01	0.00001	-	-	-	346R
*346B	1 00	0.0001	-	-	-	3460
3460	-	-	5952	4 50	0 0045	-
353A	0.01	0.00001	6026	0.50	0.0005	-
358A	-	-	6026	0.05	0.00005	-
359A	0.01	0.00001	6013	1.20	0.0012	-
372A	0.01	0.00001	-	-	-	426A
376A	0.10	0 0001	-	-	-	376B
*376B	1.00	0.001	-	-	-	3760
376C	-	-	5952	4.00	0.004	-
395A	0.01	0.00001	6039	1.60	0.0016	-
411A	0.01	0.00001	-	-	-	425A
*413A	1.00	0.001	-	-	-	413B
413B	-	-	5952	4.40	0.0044	-
423A	0.01	0.00001	-	-	-	423C
*423B	0.50	0.0005	-	-	-	423C
423C	-	-	6052	4.50	0.0045	-
425A	0.01	0.00001	6026	2.10	0.0021	-
426A	0.01	0.00001	6013	2.00	0.002	-
427A	0.10	0.0001	6039	4.00	0.004	-
*430A	0.50	0.0005	-	-	-	430B
430B	-	-	5952	4.50	0.0045	430C
430C	-	-	7226	15.00	0.015	-
432A	0.01	0.00001	-	-	-	432B
432B	0.01	0.00001	6052	4.50	0.0045	-
439A	0.01	0.00001	6139	3.00	0.003	-
443A	0.01	0.0001	6013	2.00	0.002	-
446A	0.10	1000.0	6026	0.10	0.0001	-
44/A	U.UI	0.00001	6026 6026	U. 10 2 10	0.0001	-
451A	U.UI	0.00001	6026 6026	2.1U	0.0021	-
453A	0.01	0.00001	6UZ6	0.30	0.0003	- Nona
^5589 6140	1.00	0.001	-	-	-	None
b14U	U.UI	0.00001	6052	4.50	0.0045	-
6141 C1C7	U. 10	0.0001	6039	4.00	0.004	-
616/	0.01	0.00001	6139	3.00	0.003	-

ł

NOTES: 1.	The date that a specific code was converted to Krypton-85 from Radium Bromide can be determined as follows:
	The year and quarter of manufacture are indicated by a four digit code. The first two digits indicate the year of manufacture and the last two digits indicate the quarter of manufacture. Example: The number 5952 marked on a tube indicates that the tube was manufactured in the last quarter (October thru December) of 1959. If the last two digits were 13, 26 or 39, this would indicate manufacture in the first, second or third quarter of any given year.
2.	Prior to the "Date Converted to KR-85", tubes contained Radium Bromide. From this "date" and later, tubes contained Krypton-85. No other criteria, including the presence or absence of the magenta three-bladed radiation symbol, shall be used to determine if a tube is a Radium Bromide or Krypton-85 tube.
3.	Cold Cathode tubes that have a three digit manufacturing code contain Radium Bromide.
4.	Cold Cathode tubes normally can be identified by the dark purplish color of the glass envelope. However, the 423 type tubes will have a <u>clear</u> glass envelope.

TABLE B



TABLE C

		TABLE C Page 1 of 1
SPARE PAC CONTAINING	KS PACKAGES (SPP'S) HAZARDOUS MATERIALS	
SPP NO.	CP'S CONTAINING MERCURY RELAY/S	CONTROLLING ORG.
SPP-831 (SxS CDA) SPP-831 (SxS CDA)	JW-95 JW-96 JW-97 JW-98 JW-104 JW-126 JW-132 JW-133 JW-149 JW-150 ED-35032-30 ED-35032-30 ED-35034-30	CB-6 CB-6 CB-6 CB-6 CB-6 CB-6 CB-6 CB-6
SPP-838 (Mini-ROTL) L-1 (SxS) (Mini-ROTL) L-1 (SxS) (Mini-ROTL) L-1 (SxS) (Mini-ROTL) L-1 (SxS) (Mini-ROTL) L-1 (SxS) (Mini-ROTL)	CP-3 ED-35115-30 CP-4 ED-35116-30 CP-6 ED-35118-30 CP-8 ED-35120-30 CP-9 ED-35131-30 CP-11 ED-35130-30	CB-6 CB-6 CB-6 CB-6 CB-6 CB-6 CB-6
L-2 (#3 ESS) (Mini-ROTL) L-2 (#3 ESS) (Mini-ROTL) L-2 (#3 ESS) (Mini-ROTL) L-2 (#3 ESS) (Mini-ROTL)	CP-6 ED-35118-30 CP-15 ED-2C551-30 CP-16 ED-2C552-30 CP-21 ED-2C554-30	CB-6 CB-6 CB-6 CB-6
L-3 (#5 Crossbar) (Mini-ROTL) L-3 (#5 Crossbar) (Mini-ROTL)	CP-4 ED-35116-30 CP-6 ED-35118-30 CP-8 ED-35120-30 CP-23 ED-27932-30 CP-24 ED-27933-30 CP-25 ED-27934-30 CP-26 ED-27935-30 CP-27 ED-27936-30 CP-28 ED-27937-30 CP-29 ED-27938-30 CP-30 ED-27939-30 CP-31 ED-27940-30	CB-6 CB-6 CB-6 CB-6 CB-6 CB-6 CB-6 CB-6

TABLE D

•

					TAB Pag	LE D e 1 of 5
			MERCURY RE	LAYS		
RELAY CODE	DE: PLUG IN	SIGN WIRE IN	UNITS PER CARTON	GRAMS OF MERCURY/ UNIT	GRAMS OF MERCURY/ CARTON	CARTON WEIGHT
275A	x		100	2,98	298.	28
B	x		100	2.98	298.	28
С	X		100	2.98	298.	28
D	Х		100	2.98	298.	28
E	X		100	2.98	298.	28
0704	<u>X</u>	+	100	2.98	298.	30
2764	, X		100	2.96	296.	35
	Ŷ		100	2.90	296	30
B	X		100	2.96	296.	31
Č	X		100	2.96	296.	31
D	X		100	2.96	296.	30
E	Х		100	2.96	296.	31
F	X		100	2.96	296.	31
G	<u> </u>		100	2.96	296.	31
H	X		100	2.96	296.	35
J	X		100	2.96	296.	31
<u> </u>			100	2.90	296	35
M	Ŷ		100	2.50	296	30
N	Ŷ		100	2,96	296.	31
R	X	1	100	2.96	296.	30
S	X		100	2.96	296.	34
T	Х		100	2.96	296.	30
U	Х		100	2.96	296.	30
W	Х		100	2.96	296.	30
Ŷ	<u>X</u>		100	2.96	296.	30
Z9ZA	X		100	2.98	298.	40
			100	2.50	298	41
29 4 A		- x	100	1.15	115.	21
B		Î x	100	1.15	115.	21
Č	X		100	1.15	115.	21
301B	X	1	100	1.15	115.	31
303A	X		100	1.15	115.	27
В	X		100	1.15	115.	27
L C	<u> </u>	-	100	1.15	115.	27
D	X			1.15	115.	27
	X		100	1.15	115.	25
+t	- <u>X</u>		100	1 15	115.	20
ы 1 1			100	1 15	115	20
ח ו	×		100	1,15	115	27
<u>к</u>	+ <u>x</u>	-+	100	1,15	115.	29
	x		100	1.15	115.	24

TABLE D Page 2 of 5

	DES	IGN	UNITS	GRAMS OF	GRAMS OF	
	PLUG	WIRE	PER	MERCURY/	MERCURY/	CARION
RELAY CODE	IN	IN	CARTON		CARION	WEIGHI #
					00.0	10
313A	ļ	Х	36	2.30	82.8	10
В		Х	36	1.15	41.4	10
С		Х	36	1.15	41.4	15
314A	<u> </u>		12	1.15	13.8	18
В	X		12	2.30	13.8	25
315A) X	36	1.15	41.4	25
316A	X		16	2.30	30.8	12
AA	ļ X		16	2.30	30.8	12
AB	<u>X</u>		16	2.30	30.8	<u> </u>
AC	X		16	2.30	30.8	9
AD	Х		16	2.30	30.8	12
AE	X		16	2.30	30.8	13
AF	X		16	2.30	36.8	12
AG	<u>X</u>	ļ	16	2.30	30.0	
AH	Х	1	16	2.30	30.0	11
В	X		16	2.30	30.0	
C			16	2.30	30.0	
D	X	1	16	2.30	20.0	15
E	<u> </u>		16	2.30	36.8	12
F	X		16	2.30	36.8	11
G	X		16	2.30	36.8	9
I H	X		16	2.30	36.8	1 10 1
J	X		16	2.30	36.8	11
K	<u> </u>		10	2.30	36.8	1
	X		16	2.30	36.8	10
M	X		10	2.30	36.8	111
N	X		10	2.30	36.8	15
P	X		10	2.30	36.8	15
R	+		16	2 30	36.8	12
5	X		16	2.30	36.8	11
			16	2 30	36.8	11
	X		16	2.30	36.8	10
W	0		16	2 30	36.8	10
2204			100	2.30	230.	22
JZUA D	l Ŷ		100	2.30	230.	23
2010	l û		100	2.30	230.	23
JZIA D	Ŷ		100	2.30	230.	23
2220	^	x I	20	2.98	59.6	11
		<u>x</u>	20	5.96	119.2	25
r r	1	x	20	8.94	178.8	25
3234		X	100	2.98	298.	23
3264		X	100	1.15	115.	14
R		x	100	1.15	115.	10
<u> </u>		X	100	1.15	115.	14
n		X	100	1.15	115.	14
F	1	X	100	1.15	115.	14
	<u> </u>			<u>.</u>		

					TAB: Page	LE D e 3 of 5
			MERCURY REL	AYS		
RELAY COD	DES PLUG E IN	SIGN WIRE IN	UNITS PER CARTON	GRAMS OF MERCURY/ UNIT	GRAMS OF MERCURY/ CARTON	CARTON WEIGHT #
328A		x	100	1.15	115.	23
B		X X	100	1.15	115.	21
C		X	100	1.15	115.	20
		X	100	1.15	115.	22
			100	1.15	115.	21
L F		x	100	1 15	115	24
Ц Н		x x	100	1.15	115.	21
J		X	100	1.15	115.	21
330A		Х	100	2.30	230.	26
В		X	100	2.30	230.	25
C			100	2.30	230.	26
			100	2.30	230.	25
3344	x	<u>+^</u>	12	1 15	13.8	15
R	X		12	1.15	13.8	16
Ĺ	X		12	2.30	27.6	16
D	X		12	2.30	26.6	16
<u>337A</u>		<u> </u>	100	0.90	90.	10
338A		X	36	1.15	41.4	16
341A			64	1.80	115.2	10
334A			100	1.80	180.	10
3454		x	100	0.05	5.	
<u> </u>		X	100	0.05	5.	3
346A		X	100	0.90	90.	5
352A		X	100	0.05	5.	5
353A		Х	100	0.10	10.	5
<u>354A</u>		X	100	0.02	2.	5
D-171584	X		100	2.98	298.	25
U-1//431	X		100	2 9 9	298	25
GA-50143	Ŷ		100	2.98	298.	35
GA-51221	x		100	2.98	298.	31
GA-52689	X		100	2.98	298.	31
GA-52909	X		100	2.98	298.	31
GA-53496	X		100	2.98	298.	35
GA-53591	X		100	1.15	115.	32
GA-53604	<u> </u>	+	100	2.98	298.	35
GA-53642	X		100	1.15	115.	29
CA-53040	Ŷ		100	2 98	298	29
GA-53998	Ŷ		100	1.15	115.	29

				TAB Pag	LE D e 4 of 5
		MERCURY	RELAYS		
RELAY CODE	DESIGN MOUNT	UNITS PER CARTON	GRAMS OF MERCURY/ UNIT	GRAMS OF MERCURY/ CARTON	CARTON WEIGHT #
KS-2145PWR	X	1	5.80	5.80	6.0
KS-5721	x	30	178.0	5340	17.0
KS-5721L-1		30	178.0	5340	17.0
997485040 KS5721L2	- <u> </u>	30	178.0	5340	17.0
KS5721L3 997485768		30 30	178.0 178.0	5340 5340	17.0 17.0
KS5721L21 997485990	<u>х</u>	30	178.0	5340	17.0
KS5721L22 997245360	x	30	178.0	5340	17.0
KS5721L54 997466875	x	30	178.0	5340	17.0
KS5721L55 997466883	x	30	178.0	5340	17.0
KS7800 99731997	x	15	370.0	5550	60.0
KS7800 997320106	х	15	370.0	5550	60.0
KS7801 997876420	x	15	370.0	5550	60.0
KS7801 997732011	x	15	370.0	5550	60.0
KS7801 997732003	X	15	370.0	5550	60.0
KS7802 997876438	х	15	370.0	5550	60.0
KS7802 997833702	x	15	370.0	5550	60.0
KS7803 997876487	х	15	370.0	5550	60.0
KS7804 997876495	X	15	370.0	5550	60.0
KS7805 997876636	х	15	370.0	5550	60.0
KS7808 997731989	X	15	370.0	5550	60.0
KS7809 997868146	x	15	370.0	5550	60.0
KS7811 997868112	x	15	370.0	5550	60.0
KS7812 997868120	х	15	370.0	5550	60.0
KS7813	х	15	370.0	5550	60.0

				TAE Pag	BLE D Je 5 of
		MERCURY	RELAYS		
RELAY CODE	DESIGN MOUNT	UNITS PER CARTON	GRAMS OF MERCURY/ UNIT	GRAMS OF MERCURY/ CARTON	CART WEIGH
K\$7816					
997862446	x	15	370.0	5550	60.
KS7817	v	15	270.0	5550	60
KS7818	<u> </u>	12	370.0	5550	60.
997862404	х	15	370.0	5550	60.
K\$7819	N.	1 5	270.0	5550	C 0
997861224	X	15	370.0	5550	<u> </u>
997861265	x	15	370.0	5550	60.
KS7822					
997833777	<u> </u>	15	370.0	5550	60.
K57823 997861455	x	15	370.0	5550	60
KS7824	~	15	370.0	5550	00.
997861331	X	15	370.0	5550	60.
KS7826	Y	10	270.0		C 0
99/8612/3 KS7927	X	15	370.0	5550	60.
997861281	x	15	370.0	5550	60.
KS7827					
997731963	X	15	370.0	5550	60.
KS7828 997861349	l v	15	370.0	5550	60
KS7829	~ ~ ~	10			
997861356	x	15	370.0	5550	60.
KS7830	, v	15	270.0		C 0
99/833/10	× ×	15	370.0	5550	60.
997833579	x	15	370.0	5550	60.
KS7832					
997833603	Х	15	370.0	5550	60.
KS/833	v	15	370.0	5550	60
KS7834		10	370.0	3330	00.
997804562	X	15	370.0	5550	60.
KS7835	, v	10	0 070		<u> </u>
997/319/1	Х	15	370.0	5550	60.

TABLE E

TABLE E Page 1 of 1

MERCURY SWITCHES

SWITCH CODE	DES PLUG IN	IGN WIRE IN	MOUNTED	GRAMS OF MERCURY/ UNIT	MAX. UNITS/ CARTON	GRAMS/ MERCURY CARTON	CARTON WEIGHT #
218A 218D 222B 223A 223B 223C		X X X	X X X	2.98 2.98 <u>2.98</u> 10.84 10.84 10.84	80 80 36 1 1 1	239 239 108 11 11 11	3 3 5 5 5 5
226B 226C 226D GA52688 GA53645		X X X X X		1.15 1.15 1.15 1.15 2.98 1.15	80 80 80 80 80 80	92 92 92 239 92	2 2 3 2

TABLE F

TABLE F Page 1 of 1

MERCURY VAPOR TUBES

Product/Type	Products per Shipping Container	Grams of Mercury/Product	Grams of Mercury per Shipping Carton
TUBES - 249A	18	0.7	13
249B	18	0.7	13
2490	18	0.7	13
253A	18	0.7	13
255A	18	2.8	50
255B	18	2.8	50
258A	18	0.7	13
258B	18	0.7	13
266A	18	2.8	50
266B	18	2.8	50
266C	18	2.8	50
267A	18	0.7	13
267B	18	0.7	13
287A	32	0.7	23
301A	32	0.7	23
314A	18	0.7	13
315A	18	0.7	13
319A	18	0.7	13
321A	18	0.7	13
323A	18	0.7	13
323B	32	0.7	23
354A	18	0.7	13
355A	18	0.7	13
393A	32	0.7	23
394A	50	0.7	35
410A	18	1.4	25

ł.

TABLE G

TABLE G Page 1 of 5

PCB CAPACITORS

CODE #	PCB WEIG POUNDS	HT PER UNIT KILOGRAMS	WEIGHT OF POUNDS	TOTAL UNIT KILOGRAMS	SPECIAL INSTRUCTIONS
287A	. 25	. 1125	5/8	. 28	See Figure 3H and Table J
287B	. 25	. 1125	5/8	. 28	See Figure 3H and Table J
287C	. 25	. 1125	5/8	. 28	See Figure 3H and Table J
288A	. 25	. 1125	5/8	. 28	See Figure 3H and Table J
288B	. 25	. 1125	5/8	. 28	See Figure 3H and Table J
289A	. 45	. 2025	1-1/2	.675	See Figure 3I and Table J
289B	. 45	. 2025	1-1/2	.675	See Figure 3K
2890	. 45	. 2025	1-1/2	.675	See Figure 3I
289D	. 45	. 2025	1-1/2	.675	See Figure 3K
290A	. 45	. 2025	1-3/8	. 6188	See Figure 3I and Table J
291A	. 45	. 2025	1-3/8	.6188	See Figure 3I
292A	. 45	. 2025	1-3/8	6188	See Figure 3I
293A	. 9	. 405	3-1/4	1.4625	See Figure 3J and Table J
293B	.9	. 405	3-1/4	1.4625	See Figure 3J
293C	.9	. 405	3-1/4	1.4625	See Figure 3L
294A	.9	. 405	3-1/4	1.4625	See Figure 3J and Table J
295A	.9	. 405	3-1/4	1.4625	See Figure 3J
296A	.9	. 405	3-1/4	1.4625	See Figure 3J
297A	2.6	1.17	7-1/4	3.26	See Figure 3F
298A	2.6	1.17	7-1/4	3.26	See Figure 3F
299A	55	24.75			See Figure 3M and Table H
300A	55	24.75			See Figure 3M and Table H
301A	55	24.75			See Figure 3M and Table H
302A	2.6	1.17	7-1/4	3.26	See Figure 3F
303A	9.5	4.275	26	11.7	See Figure 3G and Table H
304A	.9	. 405			See Figure 3Q
304B	. 9	. 405			See Figure 3Q and Table J
305A	.1	. 045			See Figure 3R
306A	. 25	. 1125		1	See Figure 3C and Table J
307A	. 05	. 0225			See Figure 3S
307B	. 05	. 0225			See Figure 3U and Table J
307C	. 05	. 0225		1	See Figure 3U and Table J
308A	2.6	1.17			

					TABLE G Page 2 of 5
			PCB CAPAC	ITORS	
CODE #	PCB WEIGH POUNDS	T PER UNIT	WEIGHT OF POUNDS	TOTAL UNIT KILOGRAMS	SPECIAL INSTRUCTIONS
310A 310B 524A D-91281 D-91282	.01 .02 .9	. 0045 . 0045 . 405			See Figure 3A and Table See Figure 3B and Table See Fg. 3T Total 2 Cans
D-96859 D-96860 D-96887 D-96963 D-96966 D-97412 D-97413	2 55 2.6 .75 .4 9.5 2.6	.09 24.75 1.17 .3375 .18 4.275 1.17	5/8 6-3/4 2-3/8 1	.28 3.0375 1.0688	See Figure 3C See Figure 3M and Table See Figure 3E See Figure 3D See Figure 3G and Table See Figure 3F
D-155002 D-157631 D-157934 D-157990 D-159047 D-160797 D-161659	.95 .9 .1 .25 .9 .25 .25 .25	.4275 .405 .045 .1125 .405 .1125 .1125 .1125			Total Two Cans See Figure 3R See Figure 3C Total Two Cans See Figure 3H
D-161832 D-161834 D-162003 D-162400 D-162860 D-162861 D-163716	.25 .45 .25 .25 .25 .25 .9 .9	.1125 .2025 .1125 .1125 .1125 .1125 .405 .405			See Figure 3H See Figure 3I See Figure 3H See Figure 3C See Figure 3I See Figure 3J See Figure 3J
D-165577 D-166602 D-169004 D-170379 D-170380 D-170381	.9 .9 1.2 .45 .45 .9	.405 .405 .54 .2025 .2025 .405			See Figure 3I See Figure 3I See Figure 3J

PCB WEIGHT WEIGHT OF TOTAL UNIT SPECIAL INSTRUCTION CODE # POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and 1 A-151997 7 3.15 See Figure 30 and 1 A-152469 55 24.75 See Figure 3P and 1 KS-5560L2 .45 .2025 See Figure 3P and 1 KS-13456 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13461 See Figure 3P and 1 See Figure 3P and 1 See Figure 3P and 1 KS-13462 .046 See Figure 3P and 1 See Figure 3P and 1 See Figure 3P and 1 KS-13461 .046 .046 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13463 .046 .046 .046 <t< th=""><th>able H able H</th></t<>	able H able H
PCB_CAPACITORS PCB_FR VELIGHT PER_UNIT VELIGHT TOTAL UNIT SPECIAL INSTRUCTION CODE # POUNDS KILOGRAMS POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and 1 See Figure 30 and 1 See Figure 30 and 1 See Figure 3P and 1 See Figure 3	S able H able H
PCB CAPACITORS CODE # POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and 1 A-151939 58 26.1 See Figure 30 and 1 A-151997 7 3.15 See Figure 30 and 1 A-152469 55 24.75 See Figure 3P and 1 GA-50451 .45 .2025 See Figure 3P and 1 KS-5560 KS-13456 .046 See Figure 3P and 1 KS-13458 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13458 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13458 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13460 .046 See Figure 3P and 1 See Figure 3P and 1 KS-13461 .046 .046 See Figure 3P and 1 KS-13462 .046 .046 .046 KS-13463 .006 .006 .006 KS-13464 .006 .006 .006 .006 KS-13470 .0	S able H able H
PCB WEIGHT WEIGHT OF PER UNIT TOTAL UNIT CODE # POUNDS KILOGRAMS POUNDS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and 1 See Figure 30 and 1 See Figure 3P and 1 See Figur	S able H able H
PCB WEIGHT WEIGHT OF TOTAL UNIT SPECIAL INSTRUCTION CODE # POUNDS KILOGRAMS POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and See Figure 30 and See Figure 30 and See Figure 30 and See Figure 30 and See Figure 3P	s able H able H
PER UNIT TOTAL UNIT CODE # POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and And A-151939 7 3.15 See Figure 30 and See Figure 3P and See Figure 3P and A-152469 55 24.75 See Figure 3P and See Figure 3P and See Figure 3P and KS-5560 .45 .2025 See Figure 3P and See Figure 3P and See Figure 3P and KS-5560 .45 .2025 See Figure 3P and See Figure 3P and See Figure 3P and KS-13456 .45 .2025 See Figure 3P and See Figure 3P and See Figure 3P and KS-13461 .45 .2025 See Figure 3P and	S able H able H
CODE # POUNDS KILOGRAMS POUNDS KILOGRAMS SPECIAL INSTRUCTION A-151939 58 26.1 See Figure 3N and See Figure 30 and See Figure 30 and See Figure 30 and See Figure 3P and See Figur	able H
A-151939 58 26.1 See Figure 3N and See Figure 30 and See Figure 30 and See Figure 3P and A-152469 55 24.75 See Figure 3P and GA-50451 .45 .2025 See Figure 3P and KS-5560 .45 .2025 See Figure 3P and KS-5560L2 .45 .2025 See Figure 3P and KS-13456 .45 .2025 See Figure 3P and KS-13456 .45 .2025 See Figure 3P and KS-13460 .046 . See Figure 3P and KS-13460 .046 . . KS-13461 .046 . . KS-13463 . . . KS-13464 . . . KS-13465 . . . KS-13466 . . . KS-13467 . . . KS-13470 . . . KS-13471 . . . KS-13473 . . . KS-13474 . . . <td< td=""><td>able H</td></td<>	able H
A-151939 58 26.1 See Figure 30 and 1 A-151997 7 3.15 See Figure 30 and 1 See Figure 3P and 1 .45 .2025 KS-5560 .45 .2025 KS-5560L2 .45 .2025 KS-13456 .645 .2025 KS-13456 .046 KS-13458 L1,2 .046 KS-13460 KS-13461 KS-13462 KS-13463 KS-13464 KS-13465 KS-13466 KS-13466 KS-13467 KS-13468 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475 <td>able H</td>	able H
A-151997 7 7 3.13 A-152469 55 24.75 GA-50451 .45 .2025 See Figure 3P and See Figur	
A-152469 55 24,73 GA-50451 .45 .2025 KS-5560L2 KS-13456 KS-13456 KS-13450 KS-13460 KS-13461 KS-13462 KS-13463 KS-13464 KS-13465 .106 KS-13466 KS-13466 KS-13468 KS-13468 KS-13469 KS-13470 KS-13470 KS-13471 KS-13472 KS-13474 KS-13475 KS-13475	able H
GA-50451 .45 .2023 KS-5560L2	
KS-5560 .046 KS-13456 .046 KS-13458 L1,2 KS-13450 .046 KS-13460 .046 KS-13461 .046 KS-13462 .046 KS-13463 .046 KS-13464 .046 KS-13465 .106 KS-13466 .106 KS-13468 .106 KS-13469 .106 KS-13469 .106 KS-13471 .106 KS-13470 .106 KS-13471 .106 KS-13471 .106 KS-13471 .106 KS-13474 .106 KS-13473 .106 KS-13474 .106 KS-13475 .106	
KS-13456 .046 KS-13458 L1,2 KS-13460 .046 KS-13461	1
KS-13458 L1,2 .046 KS-13458 L1,2 .046 KS-13460 KS-13461 KS-13462 KS-13462 KS-13464 KS-13465 KS-13466 .106 KS-13466 .106 KS-13467 .106 KS-13468 .106 KS-13469 .106 KS-13469 .106 KS-13470 .106 KS-13471 .106 KS-13472 .107 KS-13473 .107	
KS-13456 L1,2 1.040 KS-13460 KS-13461 KS-13462 KS-13463 KS-13465 .106 KS-13466 .106 KS-13466 .106 KS-13467 .106 KS-13468 .106 KS-13469 .106 KS-13470 .106 KS-13471 .106 KS-13472 .107 KS-13473 .107	
KS-13460 KS-13461 KS-13462 KS-13463 KS-13464 KS-13465 S-13466 KS-13466 KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475	
KS-13461 KS-13462 KS-13463 KS-13464 KS-13465 S-13466 KS-13466 KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475	1
KS-13462 KS-13463 KS-13464 KS-13465 KS-13466 KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13473 KS-13475	
KS-13464 KS-13465 KS-13466 KS-13467 KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475	
KS-13465 .106 KS-13465 .106 KS-13467	
KS-13466 KS-13467 KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13472 KS-13473 KS-13474 KS-13475 KS-13475	
KS-13467 KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475 KS-13475	
KS-13468 KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475 KS-13475	
KS-13469 KS-13470 KS-13471 KS-13472 KS-13473 KS-13474 KS-13475 KS-13475	
KS-13470 KS-13471 KS-13471 KS-13472 KS-13472 KS-13473 KS-13474 KS-13475 KS-13475 KS-13476	
KS-13471 KS-13472 KS-13473 KS-13474 KS-13475	
KS-13472 KS-13473 KS-13474 KS-13475	
KS-13473 KS-13474 KS-13475	
KS-13474 KS-13475	
KS-13475	
K5-13476	
KS-13499	
KS-13550	
KS-13547 L10 .096	
KS-13548 L2 .102	
KS-13549 L2 .228 See Table J	
KS-13550 L2, L3 .402	
KS-13551 L2 .63/	

						TADIE C
						Page 4 of
		D		TTODC		
		<u> </u>	LD LAPAL	TIORS		
	PCB V	EIGHT	WEI	GHT OF		
CODE #	PER	UNII	TOT	AL UNIT		
	PUUNUS	KILUGRAMS	POUNUS	KILOGRAMS	SPECIAL INSTRUCT	IONS
KS-13553						
KS-13554		1				
KS-13555						
KS-13555 L1	. 769					
KS-13558		L				
KS-13559						
KS-13950	1.36					
KS-13967 L1	50.					
KS-13982 L1	. 584					
KS=141/9 L1	1.05					
KS-14250 LI	. 637				See lable J	
KS-14433 L1	2 53					
KS-14536 I 1	672				See Table 1	
KS-16488 L1	.232				See Table 0	
KS-16704 L1	1.6	.72			See Table J	
KS-16704 L2	. 18	. 081			See Table J	
KS-16704 L3	. 36	. 162			See Table J	
KS-16704 L4	. 50	. 225			See Table J	
KS-16/04 L5	1.8	.81			See Table J	
KS-16/04 L6	1.5	.6/5			See Table J	
KS-16704 L/	. 12	.054			See Table J	
N3°10/U4 L8 KS-16702 L1	. 32	. 144			See lable J	
KS-16782 12	.05	. 0225			See Table J	
KS-16782 L2	05	0225			See Table J	
KS-16782 14	.03	.0225			See Table J	
KS-16782 L5	.05	.0225				
KS-16801 L1	.40	. 18			See Table J	
KS-16801 L2	. 80	. 36				
KS-16840 L1	. 28	. 126			See Table J	
KS-16840 L2	. 25	. 1125			See Table J	
KS-16840 L3	. 12	. 054			See Table 1	

					TABLE G
					Page 5 of
		79	R ΓΔΦΔΓ	TTORS	
		<u></u>	0 0/11/10	110110	
	PCB WE	IGHT	WEI	GHT OF	
	PER L	INIT	TOT	AL UNIT	
<u>CODE #</u> 1	POUNDS	TLOGRAMS	POUNDS	KILUGRAMS	SPECIAL INSTRUCTIONS
KS-16840 14	. 41	. 1845			See Table J
KS-16840 15	. 22	. 099			See Table J
KS-16840 L6	. 21	. 0945			See Table J
KS-16840 L7	. 30	. 135			See Table J
KS-16840 L8	. 14	. 063			See Table J
KS-16840 L9	1.1	. 495	ļ		
KS-16840 L10	. 23	. 1035			Car Table 1
KS-16840 L11	. 14	.063			See Table J
KS-16840 L12					
KS-16840 L13		144			See Table 1
KS-16840 L14	. 32	. 144			See Table 0
KS-16840 L15					Soo Table 1
<u>KS-16840 L16</u>	.53				See Table J
KS-16840 L1/	. 12	216			See Table J
KS-16840 L18	.48	.210			See Table J
KS-10840 L19	17	765			See Table J
KS-19300 L1	1.7	3465			See Table J
KS-19300 LZ	.,,	0405			See Table J
KS-19388 LA	17	765			
KS-19388 15	2.2	.99	+	1	
KS-20588 11	.40	.207			See Table J
KS-20588 12	. 25	. 1125	1		See Table J
KS-20588 L3	. 34	. 153	1		See Table J
KS-20588 L4	1.56				
KS-20588 L5	.78	. 351			
KS-20588 L6	1.8	. 81	1		
KS-20588 L7	. 60	.27	1	1	
KS-20588 L8	. 16	.072			
KS-20588 L9					
KS-20588 L10					
KS-20588 L11	. 68	. 306			See ladle J
KS-20588 L12	.15	.0675			
KS-20934 L1	. 38	.171	1		

TABLE H

TABLE H Page 1 of 1

CAPACITORS AND CONDENSERSOVER THREE POUNDS (1.35 KILOGRAMS)

PCB	WEIGHT
POUNDS	KILOGRAMS
55	24.75
55	24.75
55	24.75
9.5	4.275
55	24.75
9.5	4.275
58	26.1
7	3.51
55	24.75
	PCB POUNDS 55 55 9.5 55 9.5 55 9.5 58 7 55

TABLE I

				rage 1	01 1
		GENERAL TRADE	NAMES		
AEROVOX					P0950F)
Letters J & F-PCB	(2095, 21386	, P142F, P150	r, P102r, P104	, 1001, 101,	
CORNELL	CM	KA	KS	ТЈ ТК	WAB WAT
DOBILIER		KK	T	ŤĹ	YAB
	KG	KN	ТА	TN	YAT
GENERAL ELECTRIC	23F 45F 49F 72F	28F 47F	Not All	PCB Types	
GUDEMAN	9800 Seri	es	95000 Se	eries	
MALLORY	23	27	31	37	
	29		J2		
SANGAMO	Type 75		Type 80		
SPRAGUE	38P 200P	201P 234P	235P 264P	355P 356P	
MILITARY SPEC				CP40	
MTL C-2E		Characterist	ic "F" Style	CP41 CP53	
MIL - C-25		Characterist	ic "F" Style	CP54	
				CP55 CP61	
				CP62	
				CP63	
				CP65	
				CP67	
		Chanactonict	ic "F" Style	CP69	
		unar acter 15t		CP72	
				CP80	
				CP81 CP82	
				CP81 CP82 CP91	

TABLE J

TABLE J Page 1 of 8

SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
80446-02	None	806A Plants - AC and battery driven 1/2 amp ringing machines with automatic transfer	287A
80606-01	86207E		310A, 310B
80606-02	86207J		310A, 310B
80606-08	86207J	Rectifier units - Regulated tube type or	310B
80620-01	86207C	semiconductor type	310A, 310B
80620-02	86207C		310A, 310B
80620-03	86207C		310A
80621-01	86578	420A Plant, 152-volt, 0 to 30 ampere loads	287A
80622-01	86578	with miscellaneous supplies - auxiliary repeater stations with ac power service	287A
80653-01	86578	420A Plant - Charge and discharge circuit - Pos. 152V plate and filament battery	287A
80709-01	None	10 and 20 party code ringing - 380A dial office	287A
80714-01	86207S	Regulated tube or semiconductor rectifier	287C
80727-01	86212P	Small ringing equipments - 355A dial office	307B
80764-01	86207M	Deculated tube meetificm	310A, 310B
80764-02	86207L	Regulated tube rectifier	310A, 310B
80779-01	None	Generator and interrupting equipment code ring- ing maching - step-by-step system	307B
80823-01	86207T	Regulated tube rectifier	294A
80855-01	86578	420A Plant - J and K carrier telephone - auxiliary station	287A
80863-01	86578G	420A Plant - K2 carrier amplifier - regular and emergency filament supply	¹ 287A
80863-02	86578G	420A Plant - K2 carrier amplifier - regular and emergency filament supply	¹ 287A, 287B
80871-01	862070	Regulated tube rectifier	306A, 310
80912-01	None	420B Plant - K2 carrier telephone - auxiliary stations	287A
80921-01	86578K	420A Plant - J, K and V1 auxiliary stations	287A

TABLE J (Continued)

TABLE J Page 2 of 8

SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
80930-01	86216A	Regulated tube rectifier phase shift control	287A
80937-01	86207W	Regulated tube rectifier	287A, 306A 310A
80940-01	None 86425A	Rectifier inverter rectifier	287A, 310A 287A, 310A
80959-01	None	420A Plant - Charge and discharge circuit	287A
80960-01	86426A	505C Plant - "L" carrier telephone	288A
80961-01	None	505C Plant - "L" carrier telephone	287A
80962-01	86217A		287A, 306A
80963-01	86218A	Demulated tube mostifion	287A
80970-01	86219A	Regulated tube rectifier	287A
80976-01	86221A		<u>287A</u>
80981-01	86431F.G	Teletypewriter switching unit No. 81C1	KS-5560, LO2
81010-01	86227A.B		287A
81010-02	86227C		287A
81010-03	86227A		287A
81011-01	86225	D	287A
81012-01	86226A.B	Regulated tube rectifier	287A
81013-01	86228A.B		287A
81046-01	86232A		287A
81058-01	86219B		287A
81075-01	86238A	AC control unit	287A, 289A
81076-01	86240A	Rectifier - Regulated tube or simiconductory type	287A, 310A, KS-14258
81077-01	86240B	Regulated semiconductor or tube type rectifier	KS-14258, 287A, 310A

> TABLE J Page 3 of 8

SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
81088-01	86244A	Semiconductor type rectifier	287A
81092-01	86621	Engine driven alternator	KS-13463, L1
81098-01	None	Regulated DC supply	306A, 294A
81110-01	86225D	Degulated tube meetifier	287A
81117-01	86226D	Regulated tube rectifier	287A
81129-01	86249ABC	Metallic type rectifier	KS-16782, L1
81208-01	86624A	Diesel engine driven alternator set - main control cabinet	KS-13463, L1
81217-01	86225E	Regulated tube rectifier	287A
81248-01	86269A	AC control unit	287A, 289A
81251-01	86460A,B D, E, F	Submarine cable power supply	287A
81252-01	86460A,B D, E, F	Submarine cable terminal plant power supply	287A
81253-01	86462B	Submaning cable neuron cumply	290A
81254-01	86462B	Submarine cable power supply	290A
81256-01	86462B	Repeatered submarine cable high voltage turndown relay	287B
81257-01	86462B	Repeatered submarine cable alarm circuit	287A
81136-01	86621A	<u>Engine driven alternator - automatic control</u>	KS-13463, L1
81138-01	86251A	Electron tube rectifier	310B
81147-01	86250A	Voltage regulator and exciter - Electronic con- trol for 24 and 40-volt motor-generator sets	KS-14536
81152-01	86447A	Power control bay - L3 carrier telephone - 505D and 521A plant	228A, 289A
81161-01	86450A,B	12-, 130- and 250-volt power supplies with and without battery reserve - 425B plant - TD-2 radio system	287A

TABLE J Page 4 of 8

	SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
	81164-01	86262A	Electronic type current regulator	287A, 288A 2 94 A
	81185-01	None	Power factor correction equipment	KS-5560
	81196-01	JB645A,B	Reserve power supply equipment - O carrier repeaters	287A
	81200-01	JB6622	Engine driven alternator - automatic control	KS-13463, L1
	81274-01	None	Charge and discharge circuit - 100 type plants	310B
	81305-01	86275A	Regulated current rectifier servo AC control	287A, 289A
	81308-01	86469A	Repeatered submarine cable power supply (positive)	290A
	81309-01	86469A	Repeatered submarine cable power supply (negative)	290A
	81310-01	JB6469	Repeatered submarine cable high current protection relay	288A
	81312-01	None	Alarm unit - repeatered submarine cable	287A, 288A
	81339-02	86473A	Power supply (TJ radio)	310A, 310B
	81350-01	86476G.H	508A plant - continuous 230-volt AC power	287A, 287B
	81369-01	86283B		KS-16704, L1
1	81369-02	86283B	Metallic type rectifier	KS-16704, L1
	81369-03	86283B		KS-16704, L1
	ES-81389 -01	86291F	Metallic type rectifier Electronic Switching System Morris, Illinois	293B
	81393-01	86260, 86261, 86284	Motor starters - 302A and 702C plants	KS-5560
	81405-01	86225F	Regulated tube rectifier	287A
	81410-01	862950	Swmiconductor type rectifier	287B
	81425-01	86486B	Metallic type rectifier	287A

		. I	TABLE J Page 5 of 8
LIS	ST OF WE	MANUFACTURED POWER EQUIPMENTS CONTAINING PCB CAP	ACITORS
SD	J	DESCRIPTION	WE AND KS TY PCB CAPACITO
81442-01	86487A	Power supply (TH radio)	287A
ES-81450 -01	None	230V AC power supply - Morris Electronic Switching System	287A
81507-01	86499	Power supply (TL-1 radio)	306A, KS-16840, KS-13550.
81509-01 81510-01 81510-02	87208A 87207A 87207B	Semiconductor type rectifier	KS-16782, KS-16840, Ks-16840,
81517-01 81519-01 81521-01	86805C 86805G 86805A	Constant current rectifiers (SD submarine cable	304B 304B 290A
81525-01 81536-01	86806A 87215A	Ground supply bay (SD submarine cable)	290A KS-16782,
81538-01 81551-01 81561-01 81564-01	87212A 87221A 87238A 87205B	Semiconductor type rectifier	KS-16782, KS-16840, KS-16782, KS-16840,
81574-01	87226A	Rectifier (ferroresonant regulation)	KS-16840, KS-16782,
81607-01 81617-01 81617-02 81622-01 81623-01	87234A 87239A 87239B 87243A 87243A	Semiconductor type rectifier	KS-16840, KS-16782, KS-16782, KS-16840, KS-16840,
81624-01 81625-01	87241A 87240A		KS-16782, KS-16782,

TABLE J Page 6 of 8

			WE AND KS TYPE
SD	J	DESCRIPTION	PCB CAPACITOR
81646-01	86819A	DC power cable supply - SD submarine cable	290A
81650-01	87235A	Semiconductor type rectifier	KS-16782, L3
81657-01	87254A	Semiconductor type rectifier	<u>KS-19388, L1</u>
81660-01	86835A,B C. D	Converter power supply (TD-3 radio system)	KS-16704, L2 L3
81675-01	87255A 87258A	Semiconductor type rectifier	KS-16840, L5 KS-16782, L1
81710-01	86831A	Power plant for small PBX system	<u>KS-16840, L7</u>
81717-01	87266A	Inverter - 20 cvcle DC-AC	<u>KS-19388, L1</u>
01721-01	872204		KS-19388, L1
01/21 01	072204		L2
01702-01	872674	Semiconductor type rectifier	KS-16840, L6
01727-01	872704		KS-16840, L3
01726-01	97272A		KS-16782, L2
01/30 01	012120	TM modio	KS-16782, L4
81741-01	86843A	Power supply for traveling wave tube (IM radio	KS-16704, L2
81743-01	86635A,C	Power supply for 801A and 850A PBX	KS-16840, L1 L4
81744-01	87274A	Semiconductor type inverter for TH radio	KS-16840, L9
81766-01	87276A	Semiconductor type rectifier	KS-16840, L5
81779-01	None	21A power supply power unit	<u>KS-19388, L3</u>
81780-01	None	17A and 17B power unit	<u>KS-16782, L3</u>
81781-01	87241B		KS-16782, L1
81789-01	87281A	Semiconductor type rectifier	KS-16782, L3
81790-01	87282A		KS-16782, L3
		DC power supply for TH radio traveling wave	KS-16704, L1
81804-01	86353A	tube	L4, L5, L6
81806-01	None	B996097 power unit	KS-16782, L3
01000 01			KS-16801, L1
81823-01	1 87295A	20Hz DC to AC inverter unit	KS-16840,
01020 0.			L12, L18

> TABLE J Page 7 of 8

SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
81829-01	87292A	Semiconductor type power supply	KS-16840, L4
81836-01	87296A	Power supply - TD3 radio repeater test set	KS-16840, L2
81850-01	87303A,H	Converter power supply for L4 coaxial system	KS-16704, L8
81854-01	None	18A power unit	KS-16782, L3
81856-01	86858B,E	Power supply for L4 coaxial system	288A
81864-01	None	26A power unit	KS-16782, L2
81867-01	87272B	Semiconductor type rectifier	KS-19388, L3
81873-01	86878A	Power supply for 761B PBX system	KS-16840, L7
81878-01	None	31A power unit	KS-16840, L5
81900-01	None	18B1 power unit	KS-16782, L3
81903-01	None	24A power unit	KS-16782, L1
81908-01	87326A	20Hz DC to AC inverter	KS-16840,
81915-01	87234B	Semiconductor type rectifier	KS-16840, L5
81947-01	None	F57529 power unit	KS-16840,L17
81975-01	87337A	20Hz DC and AC inverter	KS-16840,L19 KS-20588, L2
81981-01	87342A	Semiconductor type rectifier	KS-20588, L1
82004-01	86890C	Converter for traveling wave tube (TD3 radio)	KS-167043, L2. L3
82009-01	87329A	Semiconductor type rectifier	KS-20588, L3
02003 02	0,020,1		KS-16704.
82018-01	868918	680A power plant	L4, L8
82054-01	87358A	805A PBX power supply	KS-16840, L6
82091-01	87381A	Regulated ferroresonant rectifier	KS-20588, L1
82101-01	None	68A power unit	KS-19388, L3
82116-01	86635D	Regulated ferroresonant rectifier	KS-20588,L11
82128-01	86899A	680B power plant	KS-16704, L8
82129-01	86899B	680B plant (L5 coaxial repeatered line)	KS-16704,

TABLE J (Continued)

TABLE J Page 8 of 8

SD	J	DESCRIPTION	WE AND KS TYPE PCB CAPACITOR
82139-01	None	91A power unit	KS-16840,L11
82228-01	None	108A power unit	<u>KS-16840, L8</u>
		112A Frequency Generator Mounted in the 800 or 801 PBX Cabinet or CSS 201 PBX	KS-16840, L8
82229-01	87412A	Line feed converter for T4M line	KS-16704, L8
82258-01	J87415A,E	20Hz DC to AC inverter	KS-16840,L16
82391-01	None	207B power unit	KS-20588, L3
82414-01	None	229A power unit	KS-20588, L3

FIGURE 1

COLD CATHODE TUBES



FIGURE 1 - (Cont'd.)

COLD CATHODE TUBES



FIGURE 2







FIGURE 2A

MERCURY VAPOR TUBES



FIGURE 3

PCB CAPACITORS





PCB CAPACITORS







PCB CAPACITORS



