

**QUALITY REVIEW PLAN
FOR
TRUNKS AND TOLL SPECIAL SERVICES**

1. GENERAL

1.001 This addendum supplements Section 010-301-001, Issue 1. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued to make a correction and add instructions to the examination of NBOC options.

2. CHANGES TO SECTION

ISSUE 1 CHANGES

2.001 On Page 23, revise paragraph 3.140 to read as follows:

3.140 Examine a minimum of 20 assigned channel units from each of the D-type channel banks

in the office. (Note: D2, D3, and some D1 channel units require circuits to be removed from service before verifying options.) Are channel unit options correct? See appropriate SD or Bell System Practice for channel unit type. Are all of the channel units associated with any one switching machine in any one office all the same NBOC option? (Note: Some channel units such as Foreign Exchange Subscriber units will not be optioned per the office balance record.) The NBOC value is determined by the guidelines set forth in Section 660-470-100 and may be obtained from the office balance record. Use Form E-6986 as a work sheet to record results of individual channel inspections.

References: Sections 365-115-500, 365-150-101, 365-150-503, 365-400-107, and 365-170-000.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

QUALITY REVIEW PLAN FOR TRUNKS AND TOLL SPECIAL SERVICES
EVALUATION AND REVIEW PROCEDURES
ADMINISTRATIVE MAINTENANCE METHODS

1. GENERAL

1.001 This addendum supplements Section 010-301-001, Issue 2. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is reissued for the following reasons:

- (a) To change the section title.
- (b) To delete "and ammeters" in paragraph 3.132.
- (c) To add paragraph 3.132.1 covering adjusting ammeters according to the power supply employed.

1.003 Issue 1 of this addendum was issued for the following reasons:

- (a) To change paragraph 5.09.
- (b) To change paragraph 5.10.

2. CHANGES TO SECTION

ISSUE 1 CHANGES

2.001 On Page 28, change paragraph 5.09 to read:

Where no records are available or their accuracy is questionable, the office has failed the quality review. Personnel charged with the maintenance

responsibility must then contact the transmission engineer or appropriate person charged with balance.

2.002 On Page 28, change paragraph 5.10 to read:

Transmission engineer or appropriate person will report results of the expanded balance survey to the Network Operations third-level manager.

ISSUE 2 CHANGES

2.003 On Page 1, in the section title, the title is changed as follows:

Quality Review Plan for Trunks and Toll Special Services, Evaluation and Review Procedures, Administrative Maintenance Methods.

2.004 On Page 23, revise paragraph 3.132 to read as follows:

Are voltmeters properly calibrated and tagged with the date of calibration?

2.005 On Page 23, after paragraph 3.132, add the following information:

3.132.1 Ammeters must be properly adjusted according to the power supply manufacturer's specifications for the individual power supply being employed.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement