

B.S.P. Released on B.S.P.M. # \_\_\_\_\_  
List S.T. 409 Date \_\_\_\_\_

LINE AND TRUNK FINDER GROUP AND CHAIN CIRCUIT  
MISCELLANEOUS TESTS  
STEP-BY-STEP SYSTEMS

1. GENERAL

- 1.001 This addendum supplements Section 226-215-500.  
1.002 It is issued to add information about slow releasing line finder switches.

4. METHOD

The following change applies to Part 4 of the section:

- (a) Step 7 — added paragraph to the verification portion.

STEP	ACTION	VERIFICATION
7		(Add the following paragraph at the end of Note 2)  Observe the time it takes each line finder to drop off. Those that do not release quickly require investigation. The usual cause is improper adjustment of the A relay. This is also a cause of ANI failure.