BELL SERVICE PRACTICES PACIFIC BELL NEVADA BELL

SECTION 218-397-916PT •Issue B, June 1984

## LINE VERIFICATION TESTS USING MASTER TEST FRAME NO. 5 CROSSBAR OFFICES ARRANGED FOR PBX DIAL TRANSFER

## 1. GENERAL

1.01 This section provides information for making line verification tests of lines and trunks appearing in the Extra Number group for Private Branch Exchange (PBX) Dial Transfer services.

**1.02** It is reissued to:

- Update the format to conform to Pacific Bell's standards.
- Include the appropriate legend on Page 1 in accordance with System Instruction (SI) 178.

*Note:* Marginal arrows used to denote changes are omitted.

**1.03** All extra number group line verification tests are made in a standard manner per Section 218-102-501 except for the following:

- (a) Operate IC-OA or OB key for all tests.
- (b) Operate TT switch on Trunk Test Circuit to ENLT.
- (c) Operate A9, B-, C-, D- keys corresponding to the tie line or trunk number.

1.04 If a trouble record card is dropped there will be no A- digit punched because the marker is directed to the extra number group by the ENLT key rather than a thousand digit. CMA punch indicates MLV-Match and NO Sleeve Check. CMB punch indicates PBX Line Busy. CMC punch indicates MLV-Match and Sleeve Check.

NOTICE Not for use or disclosure outside Pacific Bell/ Nevada Bell except under written agreement