# **BELL SERVICE PRACTICES**

ADDENDUM 232-090-024PT 
•Issue A, June 1985

PACIFICE BELL
NEVADA BELL

# **SERVICE FRAMES**

# NO. 2/2B "ESS" SWITCH

# 1. GENERAL

1.001 This addendum supplements American Telephone and Telegraph, Inc. (AT&T) Task Oriented Practice (TOP) Section 232-090-024.

# 1.002 It is issued to:

- Change step 3B, NTP 003 to read: Remove AMA tape from recorder if tape has reached EOT marker (TTY response MR AM EOF fg hi EOT t) "DLP 502".
- Delete step 3C.