



**L MULTIPLEX TERMINALS
COMMON EQUIPMENT
GROUP CONNECTOR
B2-TYPE—OUT-OF-SERVICE TESTS**

1. GENERAL

1.001 This addendum supplements Section 356-020-503, Issue 3. The attached pages must be inserted in the section in accordance with the filing instructions above.

1.002 This addendum is issued (a) to add information required to avoid STE interference with the 104.08-kHz pilot when the pilot is inserted locally and (b) to correct the labeling in Fig. 7.

CHARTS 1 and 2

The following changes apply to this section:

- (a) Step 13, Chart 1—revised
- (b) Step 12, Chart 2—revised
- (c) Fig. 7—revised

Attached:

**Page 7 dated August 1973, revised
Page 8 dated August 1973, reissued
Page 9 dated August 1973, reissued
Page 10 dated August 1973, revised
Page 15 dated August 1973, revised**