

SERVICE
2702B, 2702BM, AND 2702BMG TELEPHONE SETS
CONNECTIONS

1. GENERAL

1.001 This addendum supplements Section 502-723-401, Issue 9. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued for the following reasons:

- (a) To show the D-180229 Kit of Parts (polarity guard) manufacture discontinued (MD)
- (b) To revise Table A
- (c) To show that 2702BM telephone sets manufactured after 6-1-82 will be marked (under or near date code) "1-PTY". This marking indicates

the set cannot be used for multiparty service connections.

2. CHANGES TO SECTION

2.001 On Page 8, Table A is obsolete. A new Table A is provided in this addendum.

2.002 On Page 1, add paragraph 1.07 as follows:

1.07 Telephone sets *not* marked "1-PTY" are adaptable for all classes of line and ringer connections. Sets marked "1-PTY" cannot be used for multiparty service connections. If service other than individual or bridged ringing is required, a 2702B2M or 2702B2MG base, housing, and handset must be ordered separately.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

TABLE A

POLARITY GUARD CONNECTIONS (SEE NOTE)

RINGER	POLARITY GUARD	WIRE OR LEAD	COLOR	REMOVE FROM NET.	CONNECT TO	
					NET.	POLARITY GUARD
M-Type Ringer	D-181063 Kit of Parts	Line Switch	W	F		T
			BR	C		S
		Polarity Guard	G		F	
			W		C	
	D-180229 (MD) Kit of Parts	Dial	BK	RR		3*
		Line Switch	BR	C		4*
		Polarity Guard	R			3*
			BK			4*
			G		RR	
			W		C	
P-Type Ringer	D-180896 Kit of Parts	Line Switch	W	F		T
			BR	C		S
	Polarity Guard	G		F		
		W		C		

Note: For use when specified by local instructions for end-to-end signaling installations.

* Terminals 3 and 4 are on terminal board which is part of D-180229 (MD) Kit of Parts.