

RELAYS (WIRE-SPRING TYPE)
REPLACING CONTACTS

1. GENERAL

1.001 This addendum supplements Section 069-310-803, Issue 8. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued for the following reasons:

- (a) To add 841068778 U-shaped contact
- (b) To rate P-10A949 U-shaped contact Manufacture Discontinued. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 1 under Material, change P-10A949 to P-10A949 (MD).

2.002 On Page 1 under Material following 840054748, add 841068778 (replaces P-10A949) U-shaped contact (for use on all fixed springs, AF-, AG-, AJ-, AK-, AL-, and AM-type relays).

2.003 On Page 14 paragraph 4.31, change (P-10A949 contact) to (P-10A949 or 841068778 contact).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement