10-, 11-, 26-, 27-, AND 32-TYPE BANKS ASSOCIATED WITH ROTARY SELECTORS REPAIRING FEEDER BRUSH TIPS USING THE NO. 1004A OR 1004B TOOL KIT

1. GENERAL

1.001 This addendum supplements Section 069-311-801, Issue 3.

1.002 This addendum is issued to specify the use of KS-19578 L1 Trichloroethane wherever KS-8372 Trichloroethylene is now specified. The same precautions that apply to KS-8372 Trichloroethylene shall apply to the KS-19578 L1 Trichloroethane.