

TEST PROCEDURES
COMPLETING MARKER CIRCUIT
ARRANGED FOR PBX DIAL TRANSFER

1. DESCRIPTION

1.1 This section describes tests to be performed on completing markers modified for PBX Dial Transfer per ST-521120.

2.3 Operate A-, B-, C-, D-, IC- (non-toll) CRU- and OA or OB keys for line under test. Operate ST key.

2.4 DISI and LK2 lamps should light. Check for RCT- and RS- punch on trouble card as follows:

2. RINGING COMBINATION TESTS

2.1 From office records select telephone numbers with types of services as follows:

- (a) Individual line, non-transfer class
- (b) Line in a hunting group, non-transfer class
- (c) Individual line, transfer class
- (d) Line in a hunting group, transfer class - including directory number
- (e) Official number, transfer class
- (f) POTS Non-transfer 2Pty tip
- (g) Non-hunting restricted
- (h) Hunting restricted
- (i) Disconnected Centrex number

<u>LINE TYPE</u>	<u>IC-</u>	<u>RCT-</u>	<u>RS-</u>
Par:			
2.1a	Non-Toll	RCT1	RSO, 6
2.1b	Non-Toll	RCT10	RSO, 6
2.1c	Non-Toll	RCT4	RSO, 4
2.1d	Non-Toll	RCT5 or 15	RSO, 5
2.1e	Non-Toll	RCT8	RSO, 8
2.1e	Toll	RCT8	RSO, 8
2.1f	Non-Toll	RCT11	RSI, 6
2.1g	Non-Toll	RCT1	PAN -
2.1h	Non-Toll	RCT10	PAN -
2.1i	Non-Toll	RCT1	PAN -

2.2 Operate Keys INC, REC, MT.

2.5 Test 2.1g, 2.1h and 2.1i are denied on incoming calls. A PAN- will be operated and will get a recorded announcement.

3. EXTRA NUMBER TRANSLATOR MODIFICATION TEST

3.1 No special tests are required for the ENT- portion of the marker. This modification will be tested when making tests of the extra Number Translator Frame.