

ALARM SERVICES DESCRIPTION

1. GENERAL

1.001 This addendum supplements Section 314-410-570, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued for the following reasons:

- (a) To delete the period at the end of paragraph 4.18, subparagraph (a)
- (b) To add the common name after the trademark in paragraph 5.01
- (c) To change the wording of paragraph 8.01
- (d) To revise the trouble clearing procedures found in paragraph 8.02
- (e) To add information regarding TELCO responsibilities in Part 10 of the section.

2. CHANGES TO SECTION

2.001 On Page 5, paragraph 4.18, subparagraph (a), delete the period at the end of the phrase.

2.002 On Page 8, paragraph 5.01, delete D from (DSAS) and add the word *service* after the parenthesis.

2.003 On Page 11, Part 8, paragraph 8.01, at the end of the first sentence, change the words *the problem* to *any problems*.

2.004 On Page 11, revise paragraph 8.02 as follows:

8.02 When trouble occurs, the alarm company will make initial tests in an effort to isolate the trouble location. Channels provided for direct current alarm services will be tested to assure that they are clear of shorts, opens, grounds, and that the presence of FEMF or leakage is within limits for a telephone service provided in the same cable. The alarm company will request the assistance of TELCO in sectionalizing the trouble in cases involving multipoint McCulloh circuits. The alarm company will be informed as to the nature of any trouble found. The alarm company will dispatch their maintenance personnel, if required, to open and test the circuit at the point of connection between TELCO and alarm company facilities. If the trouble is in the alarm company portion of the circuit or equipment, the alarm company will repair the fault and notify TELCO. No circuit will be opened or worked on by TELCO personnel unless the alarm company reports a case of trouble to the control office or specifically releases the circuit.

2.005 On Page 11, add paragraph 10.02 regarding TELCO responsibilities.

10.02 The TELCO will provide a suitable McCulloh termination unit, located at the protected location interface, on all new channel terminations providing McCulloh service. This unit facilitates the prompt clearance of troubles and assists in determining whether a trouble is in TELCO facilities or customer-provided equipment.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement