TL-1 MICROWAVE RADIO

RECEIVER TESTS

MISCELLANEOUS OUT-OF-SERVICE CHECKS

1. GENERAL

- 1.001 This addendum supplements Section 409-306-505, Issue 2.
- **1.002** This addendum is issued for the following reasons:
 - (a) To update the apparatus list to include the 70B power meter needed to perform procedures outlined in Chart 3.
- (b) To change Fig. 2 to incorporate the use of the 70B power meter in the AGC performance test.

2. CHANGES TO SECTION

- 2.001 On Page 2, preceding Chart 1 add 70B power meter to the apparatus list.
- 2.002 On Page 12, Chart 3, replace existing Fig. 2 with new Fig. 2.




Fig. 2—J99351E IF Amplifier Unit—AGC Performance Test—Test Setup Diagram